First reviewed: March 28, 1991 lecommend: N Reviewed: 12/17/91
Reviewed: 12/17/91
Recommend: NFRAP:

PRELIMINARY ASSESSMENT

Dietrichs Industrial
LITTLE FERRY BOROUGH, BERGEN COUNTY
EPA ID No.: NJD986603686



New Jersey Department of Environmental Protection Division of Hazardous Waste Management Bureau of Planning and Assessment

DIETRICHS INDUSTRIAL SITE DIETRICHS STREET LITTLE FERRY, BERGEN COUNTY, NEW JERSEY EPA ID # NJD986603686

TABLE OF CONTENTS

NARRATIVE

MAPS

- UNITED STATES GEOLOGICAL SURVEY (USGS) TOPOGRAPHIC MAP -WEEHAWKEN QUADRANGLE
- 2. SITE MAP
- TAX MAP
- BERGEN COUNTY ROAD MAP
- 5. NEW JERSEY ATLAS BASE MAP SHEET 26
- 6. NEW JERSEY ATLAS GEOLOGICAL OVERLAY SHEET 26
- 7. NEW JERSEY ATLAS WATER SUPPLY OVERLAY SHEET 26
- 8. WATER WITHDRAWAL POINTS MAP

ATTACHMENTS

- A. AFFIDAVIT TO OBTAIN APPLICABILITY/NONAPPLICABILITY DETERMINATION PURSUANT TO ECRA, APRIL 20, 1987.
- B. RESPONSE TO THE APPLICABILITY AFFIDAVIT, MAY 6, 1987.
- C. AFFIDAVIT TO OBTAIN APPLICABILITY/NONAPPLICABILITY DETERMINATION PURSUANT TO ECRA, MARCH 25, 1988.
- D. RESPONSE TO THE APPLICABILITY AFFIDAVIT, APRIL 5, 1988.
- E. SOIL BORING REPORT, JUNE 27, 1988.
- F. MEMO RE: NO LANDFILL ON SITE, JANUARY 2, 1989.
- G. LETTER RE: CHEMICALS DUMPED ON SITE, FEBRUARY 22, 1989.
- H. LETTER RE: SEWAGE TREATMENT PLANT ON SITE, FEBRUARY 28, 1989.
- I. SOILS INVESTIGATION, APRIL 14, 1989.
- J. LETTER RE: PRE-SAMPLING ASSESSMENT, MARCH 22, 1991.

NARRATIVE

DIETRICHS INDUSTRIAL SITE DIETRICHS STREET LITTLE FERRY, BERGEN COUNTY, NEW JERSEY EPA ID # NJD986603686

GENERAL INFORMATION AND SITE HISTORY

Dietrichs Industrial is a 8.76-acre site identified as Block 107, Lots 2.01 and 17 on the municipal tax map. The site is bordered to the north by Dietrichs Street, to the east by the Hackensack River, to the south by a former Andrill Oil Corporation tank farm (now vacant land) and to the west by residential homes.

The owners of the site have been as follows:

1974-1980 1980-1988 March 1988-May 1988 May 1988-Present Industrial Center of Little Ferry Inc. Nejer Development Inc. Maiden Lane Corporation Frank M. & Margaret M. Notarangelo

There are approximately 35,200 residents within 1 mile of the site and an estimated 303,000 reside within 4 miles of the site.

The subject site was the location of the Little Ferry Sewage treatment plant from approximately 1940 to 1961. No other operations are known to have been conducted on site. The area is zoned for general industrial use.

SITE OPERATIONS OF CONCERN

On April 20, 1987 Nejer Development submitted to the New Jersey Department of Environmental Protection (NJDEP), Division of Hazardous Waste Management (DHWM), Bureau of Industrial Site Evaluation (now known as the Bureau of ECRA Applicability and Compliance) an affidavit to obtain an applicability/nonapplicability determination from the NJDEP pursuant to the Environmental Cleanup Responsibility Act (ECRA). The affidavit was submitted in preparation of sale of the property to Town and Country Developers, Inc. (This sale was not executed because title and deed records indicate the property was sold by Nejer Development to Maiden Lane Corporation on March 1, 1988.) The affidavit stated that the property has been vacant since the mid 1960s. Prior to this time, the property was the site of a Little Ferry sewage treatment plant. Subsequent to the plant closure and demolition, the site was filled with miscellaneous material from various sources.

On March 25, 1988 Maiden Lane Corporation submitted to the NJDEP, DWHM, ECRA an applicability/nonapplicability affidavit. This was done in preparation of sale of the site to Frank and Margaret Notarangelo. The operations at the site were listed as vacant land. The previous owner was listed as Nejer Development and their operations were also listed as vacant land.

On April 5, 1988 the NJDEP, DHWM responded to the affidavit with a letter of nonapplicability stating that this decision was made in light of the absence of an industrial establishment as defined within the Standarad Industrial Classification numbers covered by the Act.

A February 22, 1989 letter from the Little Ferry Planning Board Clerk to NJDEP, DHWM, Bureau of ECRA Applicability and Compliance stated, "various chemicals were dumped on this site." According to a letter dated February 28, 1989 from the Little Ferry Planning Board Clerk to the NJDEP, DHWM, the property was the site of a sewer plant operated by the Borough between approximately 1930 and 1957.

On April 1, 1989 soil samples were collected from seven locations at the site by Allied Environmental Industries Corporation of Fairfield, New Jersey. This sampling was conducted in response to a citizen complaint that drums were disposed of on site some 30 years ago. The town removed the drums but the contents of the drums were unknown. The samples were analyzed for volatile organic compounds (VOCs) and petroleum hydrocarbons (PHCs). The results of the sample analysis indicated the presence of PHCs at five locations ranging from 15 parts per million (ppm) to 514 ppm. Current Township officials stated that they had no knowledge of dumping occurring on site. For a detailed discussion of this sampling episode, see the Soil Section of this report.

According to the Hackensack Meadowlands Development Commission (HMDC) Project Manager for Dietrichs Industrial, the actual location of the Little Ferry Sewage Treatment Plant was directly south and adjacent to the subject site. The HMDC Project Manager also stated that he had received allegations of chemical dumping, but after inspecting the property concluded that there was no reason to believe that chemicals were disposed of on site.

On April 8, 1991 the NJDEP, DHWM, Bureau of Planning and Assessment (BPA) personnel conducted a Pre-Sampling Assessment (PSA) of the subject site. BPA personnel were met by Bill Fourgerel, a representative for the owner, and Lois Spagnola, the environmental consultant for the owner. following information was obtained during the PSA. The property is covered with demolition debris from an unknown source. Vehicle access to the property is now restricted by a pile of dirt at the entrance; this was done in attempt to prohibit further dumping. No evidence of drums, chemical Readings greater than dumping or areas of stressed vegetation were noted. 1,000 ppm as calibrated to methane were noted on the Organic Vapor Analyzer (OVA) in the area adjacent to the river. The slam bar was coated with an oil like substance when it was pulled out of the ground in the area adjacent to the river, and a petroleum hydrocarbon odor was noted. Only one reading of 3 ppm as calibrated to benzene was detected on the HNu Photoionization Detector (HNu).

BPA personnel were also met by the Project Manager for the Hackensack Meadowlands Development Commission. The Project Manager stated that the property adjacent to the site was the Andrill Oil Corporation, a tank farm that underwent an ECRA cleanup (ECRA Case #84117) in 1987. According to the ECRA case manager, a major soil remediation occurred at Andrill to remove soils contaminated with PHCs. Groundwater was also contaminated with PHCs and base/neutrals. Andrill may be a potential source of the PHC contamination of the subject site.

On April 17, 1991 NJDEP, DHWM, BPA personnel conducted an historical aerial photograph review of the subject site. Photographs taken in 1940, 1951, 1953, 1961, 1972, 1974 and 1978 were reviewed. The 1940 through 1961 photograph cleary showed that a sewage treatment plant was operated on site during those years. Several buildings, tanks, piping and three setting lagoons with separators were visible in the photographs. The 1961, 1972 and 1974 photographs revealed many areas of solid waste debris with many objects which appear to be 55-gallon drums. Disturbance and stressed vegetation were also visible in the 1972 and 1974 photographs. Only three drum-like objects appear in the 1978 aerial photograph.

On May 23, 1991 NJDEP, DHWM, BPA personnel conducted a second PSA to determine if sampling is warranted in the areas of drum disposal discovered in the 1961, 1972 and 1974 aerial photographs. No evidence of drums, chemical dumping or areas of stressed vegetation were noted. No readings were detected on the HNu or OVA.

GROUNDWATER ROUTE

A series of six soil borings were made on the site in August 1972, two in January 1984 and three additional borings were completed in June 1988 by Johnson Soils Engineering Company of Ridgefield, New Jersey. The borings were made in preparation of construction of a warehouse.

The soil borings revealed that the site lies within an area designated as tidal marsh of marine origin, composed of silty clays deposited during the recession of the Wisconsin glacier. The site has been filled with miscellaneous fill consisting of cinders, sand, silt, wood, bricks, etc. The fill depths ranged from 2 to 12 feet. Organic silt and/or peat was encountered below the fill material. Silty sand was encountered below the organic layers. Below the fill, organic and sand layers, typical varved silt and clay formations of the Meadowlands were encountered. A varve is an annual deposit usually consisting of two layers, one of fine materials and the other of coarse.

Glacial till formations, consisting of red brown silty gravelly sand, were encountered below the varved silt and clay at depths of 85 to 91.5 feet. Till is an unsorted mixture of sand, gravel, silt and clay deposited directly from the ice. The thickness of the till is variable; it averages 25 feet and is known to exceed 165 feet locally in the meadows area. Till covers almost all the bedrock in the Hackensack River Basin.

Bedrock in the Hackensack River Basin is composed of sedimentary and igneous rock of the Newark Group of Triassic age. The Brunswick Formation of the Newark Group is composed of mudstone, siltstone and sandstone and is the most important bedrock aquifer in the basin. Water occurs in this formation in a network of interconnected openings formed along joints, fractures and solution openings. The zone in the Brunswick Formation that contains fresh-water-bearing openings is generally less than 200 feet thick in the main valleys of the Hackensack River.

The Stockton and Lockatong Formations of the Newark Group have very limited aerial extent and are not important aquifers in the basin.

There are no monitoring wells on site.

There are no public supply wells within 1 mile of the site. Public supply wells within 4 miles of the site are as follows:

			DISTANCE
		GEOLOGIC	FROM
WELL OWNER	DEPTH (ft.)	FORMATION	SITE (mi)
Hackensack Water Company	550	Brunswick	2.2
Hackensack Water Company	350	Brunswick	2.7
Hackensack Water Company	235	Brunswick	2.6
Hackensack Water Company	168	Stratified Drift	4.0
Hackensack Water Company	190	Stratified Drift	4.0
Lodi Borough	300	Brunswick	3.8
Lodi Borough	307	Brunswick	3.7
Lodi Borough	300	Brunswick	3.7
Lodi Borough	332	Brunswick	3.7
Lodi Borough	373	Brunswick	2.9
Lodi Borough	409	Brunswick	3.1
Lodi Borough	607	Brunswick	3.8
Lodi Borough	459	Brunswick	3.7
Lodi Borough	470	Brunswick	3.2
Wallington Borough	400	Brunswick	3.9
Wallington Borough	400	Brunswick	3.4

The Hackensack Water Company maintains five wells located within 4 miles of the site. Hackensack Water Company operates an interconnected system of wells which serve approximately 750,000 people. These wells are not currently in service due to operational considerations and are only used in time of drought. The other wells in this system are located more than 4 miles from the site.

According to a 1987 NJDEP, Division of Water Resources (DWR), Bureau of Enforcement and Regulatory Services (BERS) Compliance Evaluation Inspection Report, Lodi Borough Water Department has closed its wells due to volatile organic contamination. Passaic Valley Water Commission has assumed operational responsibility via a contractual agreement.

According to a 1990 NJDEP, DWR, BERS Compliance Evaluation Inspection Report, Wallington Borough Water Department's municipal wells are permanently out of service due to volatile organic contamination. Wallington Borough purchases water from the Passaic Valley Water Commission.

The private potable wells located within 1 mile of the site are as follows:

DISTANCE/DIRECTION	
FROM	DEPTH (ft.)
SITE (mi)	DEFIN (IC.)
0.75/NW	130
0.50/SW	180
0.80/SW	101 *
0.80./SW	unknown

DISTANCE/DIRECTION FROM SITE_(mi)

DEPTH (ft.)

0.80/SW 1.0/SE 120 90

* Well is used for sprinkling and washroom because the water has a fuel oil taste and odor.

Numerous industrial wells are located within 4 miles of the site.

No permits were issued to any owner of the site for a discharge to groundwater.

A potential for groundwater contamination due to past site operation exists if the soil is contaminated with petroleum hydrocarbons as indicated by the April 1989 soil sampling previously mentioned. Also, groundwater may become contaminated with compounds other than PHCs due to the drum disposal that was noted in the 1961, 1972 and 1974 aerial photographs.

SURFACE WATER ROUTE

The site is bordered to the east by the Hackensack River. The Hackensack River originates in New York State and flows south for approximately 11 miles before entering Newark Bay. This region of the state is very populated; major cities downstream of the site include Secaucus and Jersey City. The major impoundments on this river, Oradell Reservoir, Lake Tappan and Woodcliff Reservoir are all located upstream from the site.

Much of the lower Hackensack watershed is tidal marshes known as the Hackensack Meadowlands. During the summer months, particularly when precipitation is deficient, brackish water from Newark Bay flows up the Hackensack River with chloride concentrations as high as 4,000 mg/l found as far north as Hackensack. This high concentration of chloride makes the water in the lower Hackensack unsuitable for potable and industrial purposes, although it is usuable for cooling purposes. About 50 percent of the land use in this watershed is undeveloped, with more than 30 percent being residential. The remainder is commercial/industrial. Waters in the lower Hackensack have been classified Saline Estuarine-2 (SE-2) and SE-3 waters. SE-2 (Saline) waters only have to meet water quality criteria for secondary contact recreation, while SE-3 waters have to allow for secondary contact recreation and the maintenance/migration of fish (not propagation).

A large number of industrial and municipal wastewater dischargers are present in the lower watershed. Twenty-six dischargers in the watershed, which are under enforcement action, are having deleterious impacts on stream water quality. Problems range from raw sewage by-passes, to illegal discharges and exceeding permit limitations. In addition, nonpoint pollution contributions from urbanized and industrial areas; landfills and sediment oxygen demand are also considered to be significant.

Based on the Hackensack Meadowlands Development Commission's sampling of the tidal Hackensack and tributaries, this region is not considered to be meeting the designated uses for SE-2 and SE-3 waters. There has been no surface water sampling relative to this site. The Hackensack Water Company has two surface water intakes on the Hackensack River. Both of these intakes are located in New Milford which is approximately 9 river miles upstream from the subject site. There are no known surface water intakes downstream of the site.

The following freshwater wetlands are located within 1 mile of the site: palustrine broad-leaved deciduous scrub/shrub, palustrine broad-leaved deciduous forested, palustrine emergent, palustrine open water and lacustrine limnetic open water. The following coastal wetlands are located within 2 miles of the site: estuarine intertidal flat, estuarine intertidal emergent, estuarine intertidal broad-leaved deciduous scrub/shrub and estuarine subtidal open water.

Federal and state threatened or endangered species in the vicinity of the site may include the pied-billed grebe, the yellow-crowned night heron, the American bittern, the northern harrier, the least tern, the sedge wren and the grasshopper sparrow.

A potential for surface water contamination exists due to run off of petroleum hydrocarbon contaminated soil. Also, soils may be contaminated with compounds other than PHCs due to the drum disposal that was noted in the 1961, 1972 and 1974 aerial photographs.

AIR ROUTE

There have been no air pollution control certificates issued relative to this site. A potential for air contamination does not exist as the site is inactive.

SOTT.

On April 1, 1989 soil samples were collected from seven locations (see site map) by Allied Environmental Industries Corporation of Fairfield, New Jersey. The samples were analyzed by Veritech Laboratories of Butler, New Jersey, NJDEP Laboratory No. 14622. Groundwater was discovered at approximately 4 feet below grade, except for Sample Location 1 (LFS 1), where it was found to be approximately 6 feet below grade. Therefore, samples included a composite of soils above and below groundwater levels encountered during sampling. Two samples were collected from Location 1 in order to determine whether there was a discrepancy in contamination levels at greater depths. The samples were analyzed for petroleum hydrocarbons (PHCs) and volatile organic compounds (VOCs).

According to the April 14, 1989 sampling report written by the President of Allied Environmental Industries Corporation, "the property is overgrown, with no visible signs of dumping; however, construction debris and rubbish were found in Locations 4A through 7A."

The following lists all sampling results:

SAMPLE #	COMPOSITE DEPTH (ft.)	ANALYSIS	RESULTS (ppm)
LFS 1A	0-4	PHC VOC	ND ND
LFS 1B	0-6	PHC VOC	ND ND

COMPOSITE DEPTH (ft.)	ANALYSIS	RESULTS (ppm)
0-4	PHC VOC	. 15 ND
0-4	PHC VOC	167 ND
0-4	DHC VOC	20 ND
0-4	PHC VOC	30 ND
0-4	PHC VOC	ND ND
0-4	PHC VOC	514 ND
	DEPTH (ft.) 0-4 0-4 0-4 0-4	DEPTH (ft.) ANALYSIS 0-4 PHC VOC PHC 0-4 PHC VOC PHC 0-4 PHC VOC PHC 0-4 PHC VOC PHC 0-4 PHC PHC PHC PHC PHC

ND = Non-detected

As the data illustrates, no VOCs were detected at any of the sample locations; PHC concentrations were detected to 514 ppm. The NJDEP soil action level is 100 ppm for PHCs. The highest level of PHCs was found in the area closest to the Hackensack River. It should be noted that asphalt was encountered in much of the debris. Also noted on the sampling report was "the former, presence of aboveground oil storage tanks to the south of the property and the presence of contaminated debris on the site."

The President of Allied Environmental Industries Corporation drew the following conclusions/recommendations based on the sampling results:

"The PHC results found were relatively low and are most probably present in this and all sites fronting the Hackensack River. The results were below the levels which the NJDEP uses to determine whether oil-contaminated soil can be disposed of in state, which is 30,000 mg/kg. Typically in cases such as this, the NJDEP would not require remediation of the soils because the area would become recontaminated as a result of continuous flooding by the Hackensack River. Based on site inspections, soil boring and analytical results, it is the opinion of Allied Environmental Industries Corporation that this property is of minor environmental concern."

Although 30,000 ppm may be the level at which soil can be disposed of in state, it in no way represents the NJDEP action level for soil which is 100 ppm for petroleum hydrocarbons.

DIRECT CONTACT

No incident of direct contact with hazardous substances has been reported. No potential for direct contact exists as the site is inactive and access to the property is restricted by dirt piled at the entrance.

FIRE AND EXPLOSION

No incidents of fire or explosion have been reported.

A potential for fire and/or explosion does not exist as the site is inactive and no hazardous or flammable materials are stored on site.

ADDITIONAL CONSIDERATIONS

There has been no reported damage to flora, fauna or off-site property; however, a potential exists if soil/subsurface contamination is present on site.

ENFORCEMENT ACTIONS

No enforcement actions were issued against the current or previous owners of the site.

PRIORITY DESIGNATION


Based on information obtained for this report, Dietrichs Industrial Site is designated a medium priority. The aerial photography revealed a sewage treatment plant on site from approximately 1940 to 1961. Also, the 1961, 1972 and 1974 photographs revealed illegal dumping including drum disposal.


RECOMMENDATIONS


No evidence of chemical dumping was found by the Hackensack Meadowlands Development Commission or by NJDEP, DHWM, BPA personnel during the April 8 or May 23, 1991 PSAs. No VOCs were detected in the samples that were collected in April 1989. Although PHCs were detected in the April 1989 samples, background levels of PHCs may be elevated due to the highly industrialized nature of the surrounding area. Readings greater than 1,000 ppm as calibrated to methane were noted on the OVA during the April 8, 1991 NJDEP, DHWM, BPA PSA. However, the elevated readings were noted in the portion of the property that was swamp. Methane is naturally occurring in subsurface wetlands environments. Sampling of this site is not warranted at this time. If evidence that the drums shown in the aerial photographs contained hazardous submstances and a release occurred becomes available, sampling may be necessary to delineate the extent of contamination.


Submitted by:


Karen Schug Hiering HSMS IV Bureau of Planning and Assessment April 10, 1991 MAPS




















•	AREA SERVED BY PRIVATE WATER SERVICE COMPANIES
	DESIGNALLY OWNED WATER SERVICE COMPANY
	THE DE MINICIPALLY OWNED WATER SERVICE COMM AND
••	AREA NOT PRESENTLY SERVED BY WATER SERVICE
ATER SUPPLY	AREA NOT PRESENTLY SERVED WAIN ACROSS HIGHW
	PUBLIC SUPPLY WELLS FOR FUTURE USE
	SURFACE WATER INTAKE :
	W MAJOR WATER MAINS
	—— W ——
inger _{Ge} #e ekker og de til ett	
	AREA SERVED BY PUBLIC SEWAGE SERVICE
	AREA NOT PRESENTLY SERVED BY SEWAGE SERVICE
	SANITARY LANDFILLS
SEWAGE, LANDFILL	SEWAGE TREATMENT PLANTS (CAPACITY < 0.3 mgd)
*	O - SEWAGE TREATMENT PLANTS (CAPACITY 50.3mgd)
•	
	*i
	DRAINAGE BASIN BOUNDARY
•	
•	RIVER BASIN BOUNDARY
DRAINAGE BASIN	HUDSON DRAINAGE BASIN NAME
DITAMAGE BITOTI	STREAMS AND RIVERS
	FLOOD PRONE AREAS
and the second s	
	COUNTY BOUNDARY
	MUNICIPAL BOUNDARY POPULATION DENSITY IN PERSONS PER SQUARE MILE
	POPULATION DENSITY IN LESS
POPULATION	CI AREA IN SQUARE MILES % PERCENT AREA OF MUNICIPALITY ON BLOCK
2	% PERCENT AREA OF MONTON
	MARKET ROADS
•	BUILT UP AREAS
	- STATE BOUNDARY
	$\mathbf{i}_{\mathbf{i}}$ (
· ·	

- INDUSTRIAL WELL YIELD OVER TO GALLONS PER MINUTE (INCLUDING PRIVATE WELLS) - PUBLIC SUPPLY WELL YIELDING OVER 70 GALLONS PER MINUTE - UNSUCCESSFUL ROCK WELL YIELDING LESS THAN 70 GALLONS PER MINUTE MAND WELL YIELDING LESS THAN 70 GALLONS PER MINUTE _ UNSUCCESSFUL - NO TEST'-, NO DATA ON YIELD FAULT (DASHED WHERE INFERRED) CONTACT (DASHED! WHERE INFERRED) PHYSIOGRAPHIC PROVINCE BOUNDARY **发展的1967年8年** STATE OF THE STATE WATER SUPPLY TRANSMISSION LINE WHERE THE PRECAMBRIAN FORMATION BOUNDARIES TERMINATE ABRUPTLY, HOTE: IT IS THE GEOLOGIST'S OPINION THAT THE GEOLOGICAL COMPLEXITY OF THE AREA PREVENTS FURTHER INTERPRETATIONS. - CRETACEOUS MAGOTHY AND RARITAN FORMATIONS (SAND AND CLAY) - TRIASSIC BRUNSWICK FORMATION Ac TRIASSIC CONGLOWERATE BEDS OF THE STOCKTON FORMATION TI --- TRIASSIC LOCKATONG FORMATION T db ----TRIASSIC DIABASE T bs ___ TRIASSIC BASALT FLOWS - SILURIAN DECKER LIMESTONE AND LONGWOOD SHALE FORMATIONS Sgp - SILURIAN GREEN POND CONGLOMERATE The transfer will be a supplied to the supplied of the supplind of the supplied of the supplied of the supplied of the supplin Omb - ORDOVICIAN MARTINSBURG SHALE alia Tan Harangali ang manda - CAMBRO ORDOVICÍAN KITTATIHNY LIMESTONE - CAMBRIAN HARDYSTON SANDSTONE PRECAMBRIAN: THE GRANDE GRANITE WITH PYROXENE GRANITE (中華) 一道 ga - AL ASKITE am- AMPHIBOLITE PX-PYROXENE GHEISS gnq-QUARTZ PLAGIOCLASE GNEISS gnb-BIOTITE GHEIS3 * - SKARN , GRAPHITE FORMATION NOT DETERMINED

LEGENU FUR ALLAS

P. Company

- A. Hackensack, Orange, Paterson, Weehawken
- B. Hackensack-Hackensack; Passaic-Saddle River, Lower Passaic

c.	2.	61 62 419	Location Passaid River at Dundee Dam, Clifton Saddle River at Lodi Weasel Brook at Clifton Fleischer Brook, East Paterson (Market Sprout Brook at Rochelle Park	St.)	Period of Record 7/23/45 1923- 1937-1961 1967- 1965-
	· 3.	242 248 264	Overpeck Creek at Ridgefield Passaic River at Garfield Saddle River at Garfield		1964- 1964 1967-

Water Quality Standards: (explained in Atlas Sheet description) FW3, TW1 except where classified TW2 or TW3

- D. Brunswick Formation
- E. 1. Physiographic Province: Piedmont
 Subdivision: Triassic Lowlands
 Major Topographic Features: Red Sandstone Plain
 Elevations (ft.above sea level): ridges 150, valleys 0
 Relief (ft.): 150
 - 2. a. Normal Year: 45"

 Dry Year: | 36"

 Wet Year: 50"
 - b. January: 31°F July: 74°F
 - c. 245 days. Last killing frost: 4/20; first killing frost: 10/20
- F. Bergen County: Saddle River County Park
- H. Von Steuben House, River Edge

I. Water Well Records

			Setting		• •		
		Year	or Depth	Total	g/m		
7	Owner	Drilled	of Casing	Depth	Yield.	Forma	tion
Location 26 02 111	Boro of Fair Lawn	<u> </u>		408	380	Trb	
D 26-03-111	11 -			458	280	11	
☐ 26-03-111 ☐ 26-03-111	11	14. 6		500	143	11	
□ 26-03-112	T to I am Defent Co. Inc.	1955	62	205	125	11	
△26-03-117	Fair Lawn Dairy Co., Inc.	1954	47	200	173	11	
口26-03-124	Fair Lawn Water Dept.	1955	48/53	400	165	11	
□26-03-127	•	1900	40/55	338	245	11	
□26-03-127				200	120	11	
	Metro Glass	1052	22	692	100	11	
$\triangle 26 - 03 - 146$		1952	22	300	304	11	
□ 26-03-161				330	95	11	
□ 26-03-171	Garfield Boro Water Dept.	1060	25	35	35	Q	
O 26-03-174	Marcal Paper Mills, Inc.	1962	·		√o test	"	
□ 26-03 - 177		1962	23		no cest	11	
□ 26-02-177		1962	8	20	11	11	
□26-03-177	"	1962	. 22	30			
△26-03-178	Sausvill'e, Ĵ. & Son			300	100	Trb	
△26-03-188		1952	79	150	75 -	11	
026-03-211	Boro of Fair Lawn			500	65	11	•
△26-03-217	Farmland Dairies, Inc.	1974	47	635	235	11	
△26-03-231	All Purpose Roll Leaf	1962	71	350	100	11	
□26-03-256		1965	77'10"	473	250		
△26-03-259				175	200	11	
△26-03-262	Alexander's Dept. Store	1961	- 25	35	290	Q	
□ 26-03-355	Hackensack Water Co.	1959		75	No test		
726-03-382				450	175	11	
△ 26-03-394		1956	135 .	145	75	Q	
△26-03-394		1958	106	120	171	Trb	
D 26-03-426	·	1954	. 80	200	180	11	
□ 26-03-427	•		· ·	400	350		
□ 26-03-453		1966	57/77	475	77	11	
□ 26-03-456		1967	33/56	400	328	п —	
O26-03-456		1966	20/43	710	30	. 11	
_		1956	54	250	312	11	
△26-03-457		1,50 [:	,	273	95	11	
□ 26-03-469	· ·	;.	:	320	130	11 .	
□ 26-03-469	t .			165	400	11	
□26-03-469	•	1966	21/40	400	25	11	
O26-03-483	•	1300	21/40	81	7	11	
○26-03-485		7067	67 5		No test	_ 11	
□ 26-03-489		1967	61.5	326	89.	11	
☐ □26-03-49 3		*				11	
△26-03-496			•	500	100	111	
△ 26-03-49		17 3 32		375	90	**	
△26-03-535	Aquarium, Inc.	1963	. 22	300	172	11	
△26-03-536	Maywood Chemical Co.			220	400	11	
△26-03-536	6 Citro Chemical Co.			220	400		
□26-03-53				403	600		•
□26-03-54		1968	15/35	405		11	
□26-03-54				300		11	
□ 26-03-54	, F			?			
☐ 26-03-54				200		••	
□ 26-03-55		1965	20/40	510	100	11	
<u>~ 2003-33</u>	- Tour not not a recommendate		•				

•	į					•
△26-03-557	Washine Chemical Co.	1966	29'4"/	400	100	Trb
	- L		46'10-1/2"	?	295	10 1
□ 26-03-561	Boro of Lodi	1960	22	· 300	290	11
△ 26-03-563	Lodi Shopping Center	1956	20'18'1	301	350	11
△26-03-563	4	1966	32	400	159	**
△26-03-563	Muscarelle, J.L., Inc.	1900	32	435	187	11
△ 26 – 03–566	Interchemical Corp.	1060	34/43	300	237	11 -
△26 - 03 - 566	Spiegal Mfg. Corp.	1969	29	400	105	11
△26-03-567	Master Etching Corp.	1965	31'5"/	459	157	tt _i
□26-03-575	Boro of Lodi	1954	53'1"	439	137	
△26-03-577	Yoo-Hoo Beverage Co.	1959	22	303	95	Ħ
□26-03-581	Boro of Lodi	•		?	145	11
□26-03-582	Lodi Dept.of Public Works	1965	36/56	450	175	11
□ 26-03-586	Boro of Lodi			?	109	11
□26-03-591	11	1966	28/48	470	285	11
D 26-03-594	tr ;			350	85	11
□ 26-03-623	Hackensack Water Co.			189	215	Q
□ 26-03-632		1954	130/	168	1700	11
-20 03 032			148'8"		-	
□26-03-632	11	1955	168	190	1420	11
\(\sigma 26-03-659\)	Bowler City	1958	120	400	108	Trb
0 26-03-667		1954	270	525	. 55	11
026-03-687	,	1965	110	400	55	11
△26-03-691		1958	115	415	76	ш
△26-03-715		1968	12/50	400	25	11
026-03-728	•			378	53	11
026-03-731	1 '	1962	90	500	25	11
△26-03-731	-	1950	76	230	100	11
O 26-03-756		1964	118.5	300	30	11
□ 26-03-768	The state of the s	1965	40	400	217	11
□ 26-03-793				300	330	11
△ 26-03-816	·	. 1957		340_	515	11
△26-03-817	· . · ·	1954	20	397	90	11
026-03-817		1954	. 31	392	20	11
△26-03-859		1952	20	145	120	11
□ 26-03-888		1955	86	86	300	Q
□26-03-888		1955		263	No test	Q
O26-03-888		1963	311/287	400	· 55	Trb
O 26-03-894	•	1955	•	243	60	Q
△26-03-899	·	1966	.53	200	100	Trb
△26-03-924		1956	67	150	95	11
△26-03-962	· · · · · · · · · · · · · · · · · · ·		A.	565	110	11
~~20~03~302	. Deage orden xum					

J. Geodetic Control Survey monuments described Index Maps 15,21; adjacent Index Map 16

Α.	Central	Park,	Hackensack,	Weehawken,	Yonkers
----	---------	-------	-------------	------------	---------

В.	Hackensack-Hackensack,	Hudson-Hudson
----	------------------------	---------------

c.	2. 1	Map No. 414	Location / Metzler Brook at Englewood	•	1965-
	3.	240 241	Hackensack River at Hackensack Hackensack River at Little Ferry Overpeck Creek at Ridgefield Rerrys Creek at Moonachie		1964- 1964- 1964- 1964-

Water Quality Standards: (explained in Atlas Sheet description) FW2, TW1 except where classified FW3 or TW2

- D. Brunswick Formation (Trb), Stockton Formation (Trs), Diabase (Trdb)
- E. 1. Physiographic Province: Piedmont
 Subdivision: Triassic Lowlands
 Major Topographic Features: Red Sandstone Plain, Palisades Ridge
 Elevations (ft.above sea level): ridges 450, valleys 0
 Relief (ft.): 450
 - 2. a. Normal Year: 44"

 Dry Year: 36"

 Wet Year: 51"
 - b. January: 32°F
 July: 74°F
 - c. 246 days. Last killing frost: 4/20; first killing frost: 10/20
- F. Bergen County:
 Overpeck County Park and Golf Course
- G. Palisades Interstate Park Commission Palisades Interstate Park
- H. Palisades Interstate Park

I. Water Well Records

			Setting				
•	i	Year	or Depth	Total	g/m		
		Drilled	of Casing	Depth	<u>Yield</u>	Format	ion
Location	i <u>Owner</u>	1958	/ 44	335	185	Trb	
△ 26-04-144	Silver Park Record Co.	1959	117'11"	147	254	Q .	
△26-04-174	Federated Dept.Stores Inc.	1968	53'3"	230	222	Trb	
△26-04-196	Englewood Hospital Assn.	1958	25	300	172	11	
△ 26-04-212	Food Fair Stores		20	-198	225	11	
△ 26-04-227	Patterson, H & Sons	1966	. 23	50	82	Trs	
△26-04-233	Grand Union Co.	•		218	89	ft	
△26-04-296	Englewood Hospital Assn.	1062	39	107	402	11	
△26-04-317	Clinton, Inn	1963	35	150	75	Trb	
△26-04-432	Grand Union Co.	1953	,	240	150	11	
△26-04-451	Home Town Laundries, Inc.	!	•	275	160	11	
□ 26-04-474	Bogota Water Co./	7070	33	168	70	?	
△ 26-04-516	Tenafly Enterprises	1970	135	145	150	Q	
△ 26-04-543		1963	64	250	\$ 100	Trs	
△26-04-556	Scharf, Charles	1955	115	298	100	11	
△26-04-557		1960	38		No test	Q	
田 26-04-744		1955	20	750	7	Trb	
O 26-04-745	Hygenic Ice Co.	1 7065	40	291	60	Trs	
O 26-04-767		1965 1972	50	300	250	Trb	
△26-04-795		1966	88-	315	200+		
△ 26-04-789	Grove Pine Corp.		30	95			
△ 26-04-799	Great Bear Spring Co.	1965	58	350		Trs	•
0-26-04-816	Leonia Board of Education	1968	00	. 33	-		

Screen

J. Geodetic Control Survey monuments described Index Maps 15,16,21

- A. Jersey City, Orange, Weehawken
- B. Hudson-Hudson; Hackensack-Hackensack; Passaic-Lower Passaic
- C. 3. Map No. Location Period of Record

 242 Berry's Creek at Moonachie, Moonachie Ave. 1964
 263 Hackensack River at Harrison, Belleville Tpk. 1967-

Water Quality Standards: (explained in Atlas Sheet description)
TW2 except where classified TW3

- D. Brunswick Formation (Trb), Stockton Formation (Trs), Diabase (Trdb), Manhattan Schist (Oms)
- E. 1. Physiographic Province: Piedmont
 Subdivision: Triassic Lowlands
 Major Topographic Features: Red Sandstone Plain, Palisades Ridge,
 Hackensack Meadows
 Elevations (ft.above sea level): ridges 250, valleys 0
 Relief (ft.): 250
 - 2. a. Normal Year: 43"
 Dry Year: 36"
 Wet Year: 53"
 - b. January: 32°F July: 74°F
 - c. 245 days. Last killing frost: 4/10; first killing frost: 10/20
- F. Bergen County: Riverside County Park and Hackensack River Area

I. Water W	ell Records		Screen			
	: :		Setting			
	1 .	Year	or Depth	Total	g/m Yield	Formation
Location △26-13-157 △26-13-177 △26-13-195 △26-13-214 △26-13-215 △26-13-216	Owner Pennick, S.B. Co. Breyer Ice Cream Co. Omni Chemical Corp. Sika Chemical Corp. Trubeck Laboratories Beckton & Dickinson Marijon Piece Dye Co.	Drilled 1966 1968 1966 1956 1966 1965 1954	of Casing 42 39 25 191 118 45 92'11"	702 300 302 201 363 285	11014 180/200 200 157 220 105 251 135	Trb " Q Trb " Q
□ 26-13-226 ○ 26-13-234 △ 26-13-268 △ 26-13-498 △ 26-13-447 △ 26-13-499	Minit-Man Auto Car Wash Food Fair Stores, Inc.	1965 1965 1957 1956 1963	70 21 39 30 66.5	220 300 400 180 320 740	60 190 115 90 82 145	Trb " " " " " " "

			i			
^ 26_13_508	Erie Railroad			184	200	Trs
	11			182	4	Trb
026-13-598	Water Finishers	1968	. 20	200	312	11
△26-13-615	Keystone Metal Finishers	1950	18	200	76	11
△26-13-642	1 "	1960	21	150	150	Trs
△26-13-655/	6 , "	1300	21	380	. 0	Trdb-Trs
026-13-668	Kiesewetter					
△26-13-695	North Bergen Realty Co.	. •		72	90	Q W1
△ 26-13-775	Fairmount Chemical Co.	1965	114	300	300	Trb
△26-13-775	United Shellac Co.			475	200	
△26-13-921	Miller & Co.	٠,		135	925	Q
026-13-924	DeAngelis Packing Co.	1948		45	0	II .
△26-13-983	Mehl, John & Co.	1913		1020	150	Trdb
026-13-983	Henri, John & Gov	1923		1050	40	. 11
_	Mountain, Ice Co.			950	0	Trdb-P6
0 26-13-984	1			1028	130	11 11
△26-13-987	Steel Laundry Co.			1350	. 0	Trs-P6
O 26-13-994	General Refrigerator			200	100	Trs
△26-13-995	Columbia; Amusement Park			200	_00	

J. Geodetic Control Survey monuments described Index Maps 21,25; adjacent Index Map 16

- A. Central Park, Jersey City, Weehawken
- B. Hackensack-Hackensack, Hudson-Hudson
- C. 2. Map No. Location
 415 Wolf Creek at Ridgefield

Period of Record 1965-

Water Quality Standards: (explained in Atlas Sheet description) TW2

- D. Brunswick Formation (Trb), Stockton Formation (Trs), Diabase (Trdb), Manhattan Schist (Oms), Serpentine (sp)
- E. 1. Physiographic Province: Piedmont
 Subdivision: Triassic Lowlands
 Major Topographic Features: Red Sandstone Plain, Palisades Ridge,
 Hackensack Meadows
 Elevations (ft.above sea level): ridges 250, valleys 0
 Relief (ft.): 250
 - 2. a. Normal Year: 47"
 Dry Year: 39"
 Wet Year: 55"
 - b. January: 32°F July: 74°F
 - c. 242 days. Last killing frost: 4/20; first killing frost: 10/20
- I. Water Well Records

	· ·						
			Year	Setting or Depth	Total	g/m	
Location	Owner		Drilled	of Casing	Depth		Formation
	Colorite Color Plastics		_ 1968	52/62	425	20	Trb
△26-14-129	Merrill Corp.			•	300	/90	Trs
	Gibraltar Corrugated Paper	Co.	1952	136	170	No test	_
026-14-147	Armour Soap Works	•		ø	116	0	Q
△26-14-148	11			i .	108	265	
$\bigcirc 26-14-173$	11			•	330	14	Trs
$\triangle 26-14-182$	Gibraltar Corrugated Paper	Co.	. 1954	105	122	300	Q
026-14-183			1950	93	528	44	Trdb
△ 26-14-742			1955	47'1"	400	105	Trs
△26-14-744	Chocolat Menier				500	125	11
	Progressive Silk Finishing	Co	•		500	125	11
~~~ZU-14-//I	Trogressite print						

Screen

J. Geodetic Control Survey monuments described Index Maps 21,16,26 --SUBJECT TO REVISION

WATER WITHDRAWAL POINTS AND NJGS CASE INDEX SITES WITHIN 5.0 MILES OF:

LATITUDE 405027 LONGITUDE 740207

## DRAFT

SCALE: 1:63,360 -(1 Inch = 1 Mile)

× WATER WITHDRAWAL POINTS

♦ NUGS CASE INDEX SITES

1 MILE AND 5 MILE RADII INDICATED

NJGS CASE INDEX DATA RETRIEVED FROM: NEW JERSEY GEOLOGICAL SURVEY ON 12/22/87

PLOT PRODUCED BY:
NJDEP
DMISSON OF WATER RESOURCES
BUREAU OF WATER ALLOCATION
CN-029
TRENTON, NJ 08625
DATE: 03/27/91

00 90 0 <del>1</del> × 20948 21728 21729 × 35800 × 5127 × 5282 ◊1244 × 4041PS × 506 405400 × 2094P 0 þ29 01161 **♦ 483** x 4006PS 2156P x 5282 x 5127 x 5086 x 5086 x 5127 ♦500 x 5127 11014006PS ogeo 5086 × 5127 ×512 %**20057#12**46 × 4025 20069 40069 5282 x 2156P ¥ 4006PS ٥ 776 x 4006PS ×5198× 224698 ×5198 0 1390 011140.868 x 2156P 1162 x 292593P x 2093P 0.592 × 205555P 762 ×23977 x 2082P x 2372P **∆474** ₹888£ × 10060W667 ♦ 660 **⊘**889 0 848 ◊832 ×9313P × 2313P x 2049P Q 437 **♦837** 404800 _¥ 2044P **≬1164** × 18379₩ 01111 0838 1243

SUBJECT TO REVISION

1 of FRELIMINARY SURVEY OF WATER WITHORAWAL POINTS WITHIN 5.0 MILES OF 405027 LAT. 740207 LON. (IN ORDER BY PERMIT NUMBER) - 03/27/91

Page

i aide	1 07 77 0000												· ·
NUMBER	VENE	SOURCEID	LOCID	LAT	ĽĞN	LLACC	DISTANCE	CCLIVITY	MTM	DEFTH	. GED1	GE02	CAPACITY
- 200 1 201 1	CARLSTADT - E. RUTHERFORD BOE	2603920	1	404931	740552	F	3.5	03	12	225	GTR#		125
10060W			+	404717	740335	T	5.9	17	'09	150	GTFB		130
10379W	KEYSTONE METAL FINISHERS, INC.		2 · . 3	404713	740336	Ť	3.9	17	09	312	GTRB		300
	KEYSTONE METAL FINISHERS, INC.	2604201	3	405220	740718	•	5.0	31	07	46	GD		175
1101D	FOSTER WHEELER PASSAIC, INC.					_	5.7	03	39	300	GTRB		80
2044F	GRAND UNION CO.	4600002		404752	740738	S			32	302	GTF®		220
2045P	SIKA CORFORATION	2504035	1	404825	740638	_ 、	4.6	03 67		490	GTRB		200
20 <b>55</b> P	GANES CHEMICAL, INC.	4600080	2	405026	740557	F	3.4	03	05				200 80
	GANES CHEMICAL, INC.	2500005	4	405024	740607	F	3.5	<u>03</u>	05	526	GTRE		
	GANES CHEMICAL, INC.	2604277	5	405025.	740557		. 3.4	03	05	430	GTRB		30
2057P	SPINNERIN YAFN CO., INC.	4600177	0	405208	740309	F	2.1	03	59	404	GTRB		ట్
	SPINNERIN YARN CO., INC.	4400083	2	405210	740305	F	2.1	೦ತ	59	435	GTRE		- O
	SPINNERIN YARN CO. INC.	2503018	3	405210	740309	'F	2.2	03	59	400	GTRE		50
	SPINNERIN YARN CO., INC.	4600176	4	405208	740305	F.	2.1	03	59	400	GTFB.		140
	SPINNERIN YARN CO. INC.		5 PROFOSED	405210	740305	F	2.1	03	59		GTRE		
20829	LOWE PAPER COMPANY	4600095	2	405005	740045	F	1.3	∙০ঙ	49	484	GTRES		50
20025	LOWE PAPER COMPANY	4600096	3	405005	740045	F.	1.3	OZ.	49	492	GTREG		75
	LOWE PAPER COMPANY	4600097	4	405005	740045	F	1.3	03	49	597	GTRBS		100
		4600078	5	405005	740045	F	1.3	03	49	500	GTREG		90 1 1
	LOWE PAFER COMPANY	4600099	6	405005	740045	F	1.3	OS:	49	600	GTRES		50 .
	LOVE PAFER COMPANY	4600006	٠ د	404936	740745	F	5.0	131 .	02	297	GTFB		235
20725	GIVAUDAN CORFORATION		7	404940	740745	F	5.0	31	02	250	GTRB		110
	GIVALDAN CORFORATION	4600007		405045	740704		4.3	03	12	580	GTRB"	•	150
209F	DRVAL KENT FOOD COMPANY, INC.	2604317	1			-	4.2	03 .	12	300	STF®		150
	CRYAL KENT FOOD COMPANY, INC.	2504341	2	405045	740654		4.2	03 - 03	12	470	GTFB		430
	ORVAL KENT FOOD COMPANY, INC.	2604382	3	405035	740655		5.9		11	<del>4</del> 70	GTRE	,	1.0.0
2094P	D.A.K. MANLFACTLRING CORP.		1	405404	740555		5.9	03	11		GTRE	•	
	D.A.K. MANUFACTURING CORP.	4600210	2	405404	740655	-			1.1		GTRB		1.0
	D.A.K. MANUFACTURING CORP.	4600211	3 .	405404	740655		5.9	্ত ংক		mers.	GTFB	,	30 ·
•	D.A.K. MANUFACTURING CORP.	2505037	4	405353	740657	F	5.8	0 <u>3</u>	11	250			750
2156F	BERGEN COUNTY FARK COMMISSION	, POND	1	405300	740000	_	3 <b>.5</b>		60	13	GOSD		750 250
	BERGEN COUNTY PARK COMMISSION	2504559	WELL 1	405210	735940		2.9	03	29	430	GTFB		125
,	BEFGEN COUNTY FARK COMMISSION	2404300	WELL 2 .	405105	740020		1.7		45	465 460	GTFB GTFB		300
2172P	FARK SO ASSOCIATES	2504234	1	405408	740530		5.7		57	400			300
	PARK SO ASSOCIATES	- 2604235	2	405410	740629		5.7	- 03	-57.7-	, 400 .	· GTRB .		0
	PARK 80 ASSOCIATES	2605301	3	405410			5.7	-03	57	300	GTRB		U
	PARK BO ASSOCIATES	2604104	4	405412			5.5		57	300	GTFB		500
.2211P	HENKEL PROCESS CHEMICALS, INC.	4600125	1	405000			2.5		05	170	GCAD		50 50
22446	ENGLEWOOD HOSPITAL ASSOCIATION	4600159	3	405409	735804	· ´F	5.5		15	334	GTFE		
	ENGLEWOOD HOSPITAL ASSOCIATION	2502435	4 .	405410	735812	F .	5.5		15	300	GTRE		100
	ENGLEWOOD HOSPITAL ASSOCIATION	2604217	5	405412	73 <b>58</b> 09	9	5.5		15	230	GTRB		200
	ENGLEWOOD HOSFITAL ASSOCIATION	2504467	5	405413	735809	) F	, 5 <b>.</b> 5		15	300	STRE		200 .
2246P	FARMLAND DAIRIES INC.	2604169	1	405134	740 <b>55</b> E	i U	3.6	03	ట్	400	STRE		200
Augin Plant	FARMLAND DAIRIES INC.	2304250	2	405134	7405 <b>5</b> 5	5 - U	3.4	OS	45	500	GTAB		185
2313P	PENCO OF LYNDHURST INC.	4600172	1	404845	740714	<b>,</b>	4.9	03	32	267	GTRE		110
المدنيت	FEVED OF LYNDHARST INC.	4600173	2	404845	740715	5	4.5	03	32	313	GTRB		185
	FENCO OF LYNCHLEST INC.	2601699	3	404845	740715	F	4.9	03	32	410	GTF®		150
٠~.	FENCE OF LYNCHURST INC.	2603804	4	404840	740705	5 F	4.8	3 03	32	352	GTRB		185
ماليمانيسنداد.	YOU-HOO CHOOCLATE BEV. CORP.	2502067	1	404946			1.7	' ৩্য	05	303	GTRE		90
2372P	YOU-HOO CHOOOLATE SEV. CORP.	2502007 ; 2502933 ·	- ·	404946			1.7	7 03	05	393	GTRE		50
	YOU-HOU CHOCOLATE SEV. COM.	2502755 2503053	Ŝ	404946			1.7	7 03	೧ವ	378	GTFB		55
		المساوعية الباقشانية	-	405003			4.9		02		GTRB		
2397P	SANDY ALEXANDER INC			405004			5.0		02		GTRE		,
	SANDY ALEXANDER INC	TO BETWEEN LIKE AND CO.	e e pares	405309			5.8		21		SEPAS		
4006FS	DUNDEE WATER FOWER & LAND CO.	DUNDEE LK/G.S.	G.S. PAPER WHIFPANY	405208			5.1		02		92		
	OUNDEE WATER FOWER & LAND CO.	CLADEE CAN	CHILTEN CO	405208			4.7		02		90		
	DUNDEE WATER FOWER & LAND CO.	DUNDEE CAN					4.		07		SP		
	DLANDEE WATER FOXER & LAND CO.	DUNDEE CAN	OKONITE,50	405143	740714	<u>- 1 .</u>	~f • /	± ب.	1417		-		

Page	2 of FRELIMINARY SLRVEY OF WAT	TER WITHDRAWAL PO	NIHTIW STNIG	5.0 MILE	S OF 405	027 LAT	. 740207 L	ON. (IN	UNDER	BY FER	MIT NUME		03/27/91	
rage N <b>LM</b> BER	NAME	SOURCEID	LCCID	LAT	LON	LAX.		ŒLNTY	MLN	DEFTH	Œ01	GE02 -	CAPACITY	!
MEMBER	1474 am		* *						02		S₽°.			
	DUNDEE WATER FOWER & LAND CO.	DUNDEE CAN	FASSAIC IN	405218	740702	T	4.8	31 			SP			
	DUNCEE WATER FORER & LAND DD.	DUNDEE CAN	TUCK IND.	405136	740704	T	4.5	31	07		SP		• •	
	DUNDEE WATER FOWER & LAND CO.	DUNDEE CAN	PANTASOTE	405204	740704	T	4.7	31	02		SFFAS			
4025FS	KALAMA CHEMICAL, INC.	PASSAIC RIVER		405206	740745	Т	5.3	03	21.		SESAD		2000	
4041FS	STEPAN CHEMICAL COMPANY	SADDLE RIVER		405355	740447		4.5	03	54	,	GTRB		180	
5086	HACKENEACK WATER COMPANY	4600065	2	405221	740157		2.2	03	04	550 350	GTFB		175	
محمد	HACKENSACK WATER COMPANY	4600066	3	405248	740143		2.7	03	04	350 235	GTRE		1/3	
	HADKENSADK WATER COMPANY	4600067	4	405242	740145	-	2.6	03	04		GOSD		1550	
5087	HADVENSACK WATER COMPANY	2500914	1	405357	740216		4.0		23	168	GOSD		1400	
رصدت	HACKENSACK WATER COMPANY	2601034	2	405355	740215		4.0		23	190	GTFS		140	
5127	LODI BOROUGH	4600068	ARNOT ST.	~405240	740518		3.8 		31	300 307	GTFB		295	
4111	LODI BOROUGH	4400069	4	405249	740502		3.7	03	31		GTEB		355	
	LODI BOROLGH	4400070	5	405249	740502		3.7		31	300	GTRB		355	
	LODI ECROUGH	4500071	7	405249	740502		.3.7		31	332	GTFB	•	500	
	LODI BOROLGH	4600072	LAWRENCE	405217	740420		2.9		31	373	GTRB		375	
	LODI BOROUGH	4600073	COLUMBIA	405240		IJ	3.1	03	31	409	GTRB		190	
	LODI BOROLGH	2601037	TERRACE	405157	740558		3.9 3.7		31 31	607 459	GTRB		150	
	LODI BOROUGH	2601010	GARFIELD	405218	740538 740301		3./ 4.9		31	450	GTRE		175 _.	
	LODI ECROUGH	2603185	HOME PLACE	405439	740435		J.2		31	470	GTFB		200	
	LODI EGROUGH	2503123	CORABELLE	405231 405131	740433		3.9		45	400	GTFB		140	
5198	WALLINGTON ECROLIGH	2600753	Du			Ŧ	3.4		65	400	STEB		150.	
	WALLINGTON BOROLISH	2603934	MAIN AVE	405130		1	4.6		తక	400	STRE		130	
	WALLINGTON BOROUGH	2603027	LESTER ST	405125		T	A.S		11	404	GTF&		100"	
5032	GASSIELD WATER DESARTMENT	4500113	1	405430			<b>5.</b> 9		11	358	GTRB		125	
	GARFIELD WATER DEPARTMENT	4600114	2 .	405430			5.8		11	350 .	GTR8		150	
	GARFIELD WATER DEPARTMENT	4600118	10	405430			5.8 5.8		11	353	GTRB		190	
	GARFIELD WATER DEFARTMENT	4600119	11	405430			5.8		11	350	GTF/B		140	
	GARFIELD WATER DEFARTMENT	45001:20	12	405430 405430	,		4.9		11	485	GTRB		140	
	GARFIELD WATER DEPARTMENT	4600121	14				6.6		11	400	GTRE		<b>6</b> 0	
	GARFIELD WATER DEFARTMENT	4600122	16 .	405430			Ó.		11	353	GTRB		110	
	GARFIELD WATER DEPARTMENT	4600123	17	405430			· 6.		11	300	GTFE		150	
	CARFIELD WATER DEPARTMENT	4600124	1	405430			5.		21	400	GTF.E		300	
	CORFIELD WATER DEPARTMENT	2504015	1A	405254			5.		21	475	GTRB		150	
	GARFIELD WATER DEPARTMENT	2504063	2	405312			4.		21	276	GTRB	-	150	
	GAFFIELD WATER DEFARTMENT	2504010	5	405209			5.		21	405	GTF#B		400	
	GARFIELD WATER DEFARTMENT	2504054	SC	405250			٥.		11	353	GTFB		90	
	GARFIELD WATER DEPARTMENT	4600115	4	405430		,	ට. පි.		11	353	GTRB		275	
	GARFIELD WATER DEPARTMENT	4600116	5	405430		•	5. 6.		11	354	GTRB		165 -	
	GARFIELD WATER DEPARTMENT	4600117	8	. 40543(	740745	: د	<b>5.</b>			:				

Number of Observations: 94

Fage 1 of NJGS CASE INDEX SITES WITHIN 5.0 MILES OF 405027 LAT. 740207 LON. AS OF 12/22/87 (IN ORDER BY DECREASING LONGITUDE) - 03/27/91

SITENUM	NAME	LAT		DISTANCE	CONTAM	FIMCODE1	FMCCDE2	STATUS1	STATUS2
174	FENICK CORP., LYNDHURST, BERGEN CO.  SKETCHLEY SERVICES, BERGEN CO.  CLRCIO SCRAP METALS, GARFIELD, SERGEN CO.  E.C. ELECTROPLATING, GARFIELD, BERGEN CO.  WALLINGTON WATER DEPT., WALLINGTON, BERGEN CO.  CLRTISS-WRIGHT CORP  J.B.M.T. FRINTING, E. RUTHERFORD, BERGEN CO.	404845	740710	4.8		0110	3070	2	J
<b>47</b> 0 .	SKETCHLEY SERVICES, REFGEN CO.	405255	740615	4.6	00	0110	3070	1	G
601	CIECTO STRAP METALS, GARRIELD, BERGEN CO.	405327	740614	5.0	50	130	3070	1	
970	E C E ECTECE ATING GARETE D. BERGEN CO.	405220	740610	4.2	O.	0	O 1	3	
1222	WALL INSTEAM WATER DEPT. WALLINGTON, BERGEN CO.	405000	740600	3.4	00	0120	3070	1	C
776	ORTISS-URIGHT OFF	405144	740547	3.5	00	3070	O	1	A
887	JUBINIT, PRINTING, E. BUTHERFORD, BERGEN CO.	404925	740535	3.3	00	0101	0100	1	B
500			740530	3.8	0	120	3070	1	· E
	•	and the state of the same of the same	740527	3.1	63	0103	0101	1 -	
474	U O P JOHNSON, FAST BUTHERFORD, BERGEN CO.	404942	740518	2.9	00 .	103	101	1	E
.775	COSAN CHEMICAL CORP. CARLSTADT. BERGEN CO.	405010	740503	2.6	00	0120	3070	1	A
488	DIAMOND SHAMFOCK, CARLSTADT, EEFGEN CO.	405017	740458	2.5	50	103	. 101	1	
368	BERRY'S CREEK FROJECT. WOODRIDGE. BERGEN CO.	405014	740448	2.4	38 -	100	. 0	1	D
550 550	SCIENTIFIC OHMICAL PROCESSING, CARLSTADT, BERGEN CO.	404928	740427	2.3	00	0110	3070	1	С.
483	INMONT CHEMICAL. LODI. EEFGEN CO.	405313	740417	3.7	00	100	3070	1	B
629	LODI/MAYWOOD RADIOLOGICAL CONTAM EGREEN CO.(SEE ALSO 500)	405345	740405	4.2	<b>67</b>	120	3070 0101	1	E
248	YORAC CO-DIV OF SEAGRAVE COATING, CARLSTADT, BERGEN CO.	404922	740405	2.1		0103	0101	1 7	В
1152	UNITED WIFE HANGER CORP. HASERCLICK HEIGHTS, BETRGEN CO.	405100	740400	1.8		0110	. 3070	ن • .	В .
838	SQUARE D CO, SECAUCUS, EERSEN CO.	404649	740330	4.4	00	OHO	. 3070	· ₹	<u>.</u>
1164	PLAZA AMOCO/KECKEY'S EXXON, SECALALS, HUDSON CO.	404729	740332	3.6 3.6				₹ .	
1161	GTE-SYLVANIA, TETEFEORO, EERGEN CO.	405330	740308	a		0103	3070	2 .	
276	GREAT BEAR STRING CO., BERGEN CO.	405200	740300	1.9 2.1		0100	3070	1	С
1246	STONE NYCAL, S. HACKENSACK, EEFGEN CC.	405210	740249	4.6		0110	3070	1	Ö
1244	RDY'S AMOOD, HACKENSACK, BERGEN CO.	405425	740230	4.0 3.9		0101	0100	1	S S
1111	FERBLECK IFON WORKS, N. EERGEN. HLDSCN CO.	404705	740217	3.7 4.8		3050	3070	1	Ē
1245	EL GIGANTE AMOCO, UNION CITY, HUDSON CO.	404515	740200	4.3 0.2		0103	0101	1	8
762	ANDRILL OIL CORP-LITTLE FERRY TER	405015	740156	0.7		0103	0100	1 .	G.
1114	RIDGEFIELD PARK EXXON, RIDGEFIELD PARK, BERGEN CO.	405102	740155	0.7		3070	0.00	1 .	3
868	TEXACO AT MAIN & PARK ST., RIDGEFIELD PARK, BERGEN CO.	405107	740130	0.9 2.7		0101	3070	1	B
837	SFONGE CLEAN FRODUCTS CO. INC. N. BERGEN, HUDSON CO.	404813	740114	2./ 1.S		0101	0	i a	F .
832	. SAM GABBAY, INC., FAIRVIEW, BERGEN CO.	404919	740007	1.3		110	3070	1	Ē
<b>57</b> 2	FFISTER CHEMICAL, RIDGEFIELD, BERGEN CO.	405030	740035	1.3 3.4		100	3070	Ô	
437	SPENCER KELLOGG, EDGENATER, EERGEN CO.	404817	735724	3.4		0100	. 3050	1	B
179	LECNIA SPILL, LECNIA, BERGEN CO.	405114	732610	2./	52 52 ·	0100	. 3050 3050	1-	B
1300	WESTGATE CONDOMINIUM CORP., FORT LEE, BERGEN CO.	405114	/35910	2./ 3.3		102	3020	Ô	_
568	CLIANTA, EDGENATER, BERGEN CO.	404905	7.55847	ن.ن م ح	ು 533	102	3070 30 <del>7</del> 0	0	
582	GENERALFOAM CORP, E. RUTHERFORD, BERGEN CO.  U O P JOHNSON, EAST RUTHERFORD, BERGEN CO.  COSAN CHEMICAL CORP, CARLSTADT, BERGEN CO.  SERRY'S CREEK FROJECT, WOODRIDGE, BERGEN CO.  SERRY'S CREEK FROJECT, WOODRIDGE, BERGEN CO.  SCIENTIFIC CHEMICAL FROCESSING, CARLSTADT, BERGEN CO.  INMONT CHEMICAL, LODI, BERGEN CO.  LODI/MAYWOOD RADIOLOGICAL CONTAM., BERGEN CO. (SEE ALSO 500)  VORAC CO-DIV OF SEAGRAVE COATING, CARLSTADT, BERGEN CO.  UNITED WIRE HANGER CORP. HASEROUCK HEIGHTS, BERGEN CO.  SCLARE D CO., SECALOUS, BERGEN CO.  FLAZA ANDOCKECKEY'S EXXON, SECALAUS, HUDSON CO.  GTE-SYLVANIA, TETERBORD, BERGEN CO.  STONE NYCAL, S. HACKENSACK, BERGEN CO.  FERUSON IRON WORKS, N. BERGEN CO.  FERUSON IRON WORKS, N. BERGEN CO.  ANDRILL OIL CORP—LITTLE FERRY TER  RIDGEFIELD PARK EXXON, RIDGEFIELD PARK, BERGEN CO.  SECANDE ATMOND, HACKENSACK, REFGEN CO.  SPONGE CLEAN PRODUCTS CO., INC., N. BERGEN, HUDSON CO.  SPONGE CLEAN PRODUCTS CO., INC., N. BERGEN, HUDSON CO.  SPONGE CLEAN PRODUCTS CO., INC., N. BERGEN, HUDSON CO.  SPONGE CLEAN PRODUCTS CO., INC., N. BERGEN, HUDSON CO.  SPONGE CLEAN PRODUCTS CO., INC., N. BERGEN CO.  SPENCER KELLOGG, EDGELATER, BERGEN CO.  LECKIA SPILL, LEONIA, BERGEN CO.  WESTGATE CONDOMINIUM CORP., FORT LEE, BERGEN CO.  LEVER BROTHERS, EDGELATER, BERGEN CO.  LEVER BROTHERS, EDGELATER, BERGEN CO.	404901	/35841	<b>3.4</b>	ಎ	1500	3070	•	

Number of Observations: 37

#### ATTACHMENT A

#### AFFIDAYTT

RECEIVED.

The purpose of 11 Department of El 13:1K-6 et seq.	his Affidavit is to obtain an applicability/nonapplicabilit nvironmental Protection pursuant to the Environmental	y determination from the New Jersey Cleanup Responsibility Act; New S.A.
		THOUSEAU OF

	the Property for which an App		
	nt. Inc. s/o Parker Cha		ol Fara
	1211 Simous of the 3		
Municipality	New York	State New York	Zip Code 10036
	equisition or Closure or Other	Relevant Transaction	May 1, 1987
5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	n request is being submitted:		
Street Address	Districts Street		
Tax Block(s)	107	_ Tax Lot(s)	L.
Municipality	Little Berry	County Berry	
State	New Jarray	Zip Code	
Describe the trans Selling, etc.), inch		2000 Company	rmination is requested (Closin

ATTACHMENT A-1

DEP USE ONLY

Name of Buriness Not 2001	licable. Site Vacant - No Structures
Address	
	County
zate Zip Code	Telephone No.
tandard Industrial Classification (SIC) No	umber Not Applicable
Tax Block(s)	Tax Lot(s)
Description of Operations and Processes (	
•	vacant since mid 1960's.
	e, the property was the site of a Little Ferry
	Subsequent to the plant closure and demolition.
	ed with miscellaneous material from various source
Unamia cha Buildhadet Hantad? Not	enni (mahi e
Section 2	applicable
Hazardous Substances or Wastes:  List all types and quantities of hazardous generated, manufactured, refined, transposet above and below ground which are is at Appendix A of N.J.A.C. 7:1E and any the Department on special waste manifest hazardous waste pursuant to N.J.A.C. 7:	substances or wastes including petroleum products that are orted, treated, stored, handled or disposed at the property.
Hazardous Substances or Wastes: List all types and quantities of hazardous generated, manufactured, refined, transposed have a special which are is at Appendix A of N.J.A.C. 7:1E and any the Department on special waste manifest hazardous waste pursuant to N.J.A.C. 7:3 sheets if necessary.)	substances or wastes including petroleum products that are orted, treated, stored, handled or disposed at the property. Included in the Department's "List of Hazardous Substances" amount of any waste substances required to be reported to the forms pursuant to N.J.A.C. 7:26-74, designated as a
Hazardous Substances or Wastes: List all types and quantities of hazardous generated, manufactured, refined, transpotent above and below ground which are is at Appendix A of N.J.A.C. 7:1E and any the Department on special waste manifest hazardous waste pursuant to N.J.A.C. 7: sheets if necessary.)	substances or wastes including petroleum products that are orted, treated, stored, handled or disposed at the property. Included in the Department's "List of Hazardous Substances" amount of any waste substances required to be reported to a forms pursuant to N.J.A.C. 7:26-74, designated as a 26-8, or as otherwise provided by law. (Attach additional

SAME AS PRESENT CANER

ATTACHMENT A-2

•	Name	Thomas M.	Zinkand	Citibank,	N.A.			7,•	
	Address						ew York	· ·	
	Value	New York							
			_ mp code ,		,		office		-
	-	CATIONS:			-	1			
	(ch (an - to 7:1 1 at 40:	Tramas M. Zineck one) at the ideny attachmobe given any fall-3 and 4 shall im fully aware to thorizes the violations of ECRA in the constant of ECRA i	above subject ents) is true. Itse information to a listing to a listing of any su of not more may be cause	ot property and I am fully away on or who falls penalty of not crized officer of provisions of a than \$25,000 for the possible.	that the in- re that any to comply more than r managem CRA or N for each o	iformation person with the S25,000 is sent official J.A.C. 7: flense. Fa if the trans	turnishe turnishe to knowing the knowing to sech out the knowing to the knowing the	a on this ngly gives of ECRA ffense. Frowingly d shall be p comply with	application or causes or N.J.A. urchermon lirects or ersonally th the pro-
				Signature of A	ffiant	Thora	m	9	
		•		Uigioni are a		4/20/8	7	7	1
					Date	11-201-	<del></del>		
	1 0 d	the owner or or ay at of on the have carefully of N.J.A.C. 7.11 illigence and an property describing ransportation. I have a	property, the said thereugh in "Discharge y appropriate and within the said and the	e following shally reviewed the consultations of affidevit do no carge, handling the consultations of the consulta	List of Ha and Other have deter or invoive or disposal	leted and liverdous S Mazardous mined tha the general of hazard	nciuded in the busing street in the busing man to be busing the busing street in the busing the business the bus	included sel" and, a sess opera ufacture, uress aborry describ	in Append after due stions on refining, we or below ed within
	g t	his efficiavit do	AR INA PROPERTY	e any amount o Si verste manace	( 20y wasu ment burs	e suestane vant to N.	J.A.C. 7:2	26-7.4, de	ngneud as
	g t	مدام ماميد آساها عناسا	AR INA PROPERTY	e any amount o Si verste manace	( 20y wasu ment burs	e suestane vant to N.	J.A.C. 7:2	26-7.4, de	त्रंकाश्वयं श्र
	g t	his efficiavit do	AR INA PROPERTY	e any amount o Si verste manace	t any wasu ament purs S, or as oth	e suestanc uant to N. termise pro	J.A.C. 7:2 wided by	26-7.4, de	zignated as
	g t	his efficiavit do	AR INA PROPERTY	e any amount o al waste manage N.J.A.C. 7:26-	tany wast iment purs S, or as oth	e suestanc uant to N. termise pro	J.A.C. 7:2 wided by	26-7.4, de	signated as
\$	9 2 2	his efficiavit do	on the specia pursuant to	e any amount o al waste manage N.J.A.C. 7:26-	tany wast iment purs S, or as oth	e sucranc usat to N. terwise pro	J.A.C. 7:2 wided by	26-7.4, de	signated as
qı	wom to an	his efficient do he Department sezardous wasti	on the specia pursuant to	e any amount o al waste manage N.J.A.C. 7:26-	tany wast iment purs S, or as oth	e sucranc usat to N. terwise pro	J.A.C. 7:2 wided by	26-7.4, de	signated as

#### ATTACHMENT B



tt

# State of New Jersey DEPARTMENT OF ENVIRONMENTAL PROTECTION

#### DIVISION OF H/ ZARDOUS WASTE MANAGEMENT

John J. Trele, Ph.D., Acting Director 401 East State St. CN 028

Mr. Thomas M. Zinkand Citibank, N.A. 399 Park Avenue New York, NY 10043 CN 028 Trenton, N.J. 08625 609 - 633 - 1408

RE: Dietrichs Street Lot 2A-2L, Block 107

Little Ferry Boro, Bergen County

#N71556

MAY 0 6 1987

Dear Mr. Zinkand:

This is in response to your letter dated 04/20/87 concerning the applicability of the Environmental Cleanup Responsibility Act (ECRA) to the sale of the above referenced premises. On the basis of the sworn statements set forth in your affidavit, the Department finds that this transaction is not presently subject to the provisions of ECRA.

This decision is made in light of the absence of an industrial establishment as defined within the Standard Industrial Classification numbers covered by the Act. Any inaccuracies in the affidavit or subsequent changes in the facts as stated therein could alter the Department's determination.

The current inapplicability of the Environmental Cleanup Responsibility Act (ECRA) to this transaction does not relieve the above referenced of any responsibilities under any other environmental statutes, regulations or permits.

Moreover, this determination of ECRA nonapplicability does not constitute any finding by the New Jersey Department of Environmental Protection as to the current site condition or the existence or non-existence of any hazards to the environment at this location.

Should you have any further questions regarding this matter, please contact Mark Fisher at (609) 633-7141.

New Jersey is An Edual Cooperation by Employer

Sincerely,

nuenced E-Talit

Michael DeTalvo, Supervisor Bureau of ECRA Applicability and Compliance

E37:dr

ATTACHMENT B

ATTACHMENT C

#### NEW JERSEY DEPARTMENT OF ENVIRONMENTAL PROTECTION DIVISION OF HAZARDOUS WASTE MANAGEMENT INDUSTRIAL SITE EVALUATION ELEMENT CN 028, TRENTON, N.J. 08625

ţ !

# ENVIRONMENTAL CLEANUP RESPONSIBILITY ACT (ECRA)

## APPLICABILITY/NONAPPLICABILITY AFFIDAVIT

The purpose of this Affidavit is to obtain an Applicability/Nonapplicability Determination from the New Jersey Department of Environmental Protection pursuant to the Environmental Cleanup Responsibility Act, N.J. S.A. 13:1K-6 et seq. and N.J.A.C. 7:268-1.9. Fee is \$100.

PLEASE TYPE OR PRINT	
	Date <u>March 25, 1988</u>
A. Determination of Applicability/Nonapplicability should be	mailed to the following:
Name Maiden Lane Corporation, c/o I	dward R. Fyans Foa
Address 8-14 Saddle River Road	•
City of Town Fair Lawn	
State New Jersey Zip Code 07410	Tele. No. (201) 794-1700
B. Name of Business Maiden Lane Corporati	on
Standard Industrial Classification (SIC) Number (if known	
C. Property Location for which request is being transmitted:	
Street Address <u>Dietrich Street and Gat</u> Tax Block(s) <u>107</u> Municipality <u>Little Ferry</u> State <u>New Jersey</u> Zip Code <u>07643</u>	Tax Lot(s) 2A, P. C, D, F, C & J
<ol> <li>Transaction for which the Applicability/Nonapplicability Det transaction)</li> </ol>	termination is requested: (Check appropriate
Business Ceasing Operations Refinancing/Construction Loan	Condemnation Bankruptcy Corporate Merger Partnership Situation Change
Date of Planned Transaction: May 2, 1988  Purchaser:	
Name Frank Notarangelo and Margaret Address 70 Pennsylvania Avenue	Notarangelo
City or Town Montvale State New Jersey Zin Code 076/5	County <u>Bergen</u>

	N/A Vacant Land.	ttach additional				
	N/A vacant Land.	· ·				
					<del></del>	
					<del> </del>	
F	Current Owner of the Property	for which on A				
•	Current Owner of the Property					
	Name Maiden Lane Co:	rporation	, c/o Ed	ward R. Ev	ans, E	sq.
	Street Address 0-14 Sac	aate Kivei	r Road	Municipalit	y Fair	Lawn
	State New Jersey	Zip Code	7410	_ Tele. No(_	201	794-1700
3.	<ol> <li>Previous Owners and histosheets, if necessary):</li> </ol>	ory of on-site	activities si	nce December	31, 1983	(Attach additiona
	Name	Ac	idress		0.00	
	Nejer Development			nuo of the		erations
	c/o Parker, Chapir	1. A	Americas	nue or the	: N/1	A Vacant Lai
	Flattau & Klimpl,			, New York		
			L0036	•		
					•	·
	•	•				
	2. Is this site currently or has th	is site previous	sly been the	subject of any o	ther FCRA	review?
			i			
	XX Previous LNA Applicat	ion .		Negative D		•
	Administrative Consent	Omer	٠.	Approved (	Cleanup P	an
			-	No prior EC	RA Revie	N
	Please submit copies of prev	vious submittal:	s or approva	ls Annexed		
_						
. !	Hazardous Substances or Was subject SIC and a subject transa	tes: (This info	rmation is o	only required if t	he facility	or business has a
t	cist all types and quantities of higher attention in the potential of the potential of the potential of the potential of the properties of	which are included and any amounts of the manifest of the control	o, treated, sided in the Dunt of any wiforms pursuited designated.	tored, handled epartment's "Lis aste substance: lant to N.J.A.C	or dispose at of Hazar s required . 7:26-74,	d at the property dous Substances to be reported to
t	20-8, or as otherwise provided	-, with (mile)	auuiliulidi	andera II N <del>ecess</del>	ary.)	,
t	226-8, or as otherwise provided			•		
t	N/A			· .		

#### J. CERTIFICATIONS:

The following certification shall be signed by the highest ranking responsibility for that site or activity. Where there is no individual bility for that site or activity, this certification shall be signed by for the overall operation of the site or activity.	al at the site with overall responsi-
the overall operation of the site of activity.	

I certify under penalty of law that the information provided in this document is true, accurate and complete. I am aware that there are significant civil penalties for knowingly submitting false, inaccurate or incomplete information and that I am committing a crime of the fourth degree if I make a written false statement which I do not believe to be true. I am also aware that if I knowingly direct or authorize the violation of N.J.S.A. 13:1K-6 et sen I an

Typed/Printed Name	Title
Signature	Date
Sworn to and Subscribed Before Me on this	
on this	
Notary	
2. The following certification shall be signed as fo	llows:
<ol> <li>For a corporation, by a principal executive</li> <li>For a partnership or sole proprietorship, by</li> </ol>	officer of at least the level of vice president;  officer at least the level of vice president;  officer of at least the proprietor, respectively; or

3. For a municipality, State, Federal or other public agency, by either a principal executive officer or ranking elected official.

I certify under penalty of law that I have personally examined and am familiar with the information submitted in this application and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate and complete. I am aware that there are significant civil penalties for knowingly submitting false, inaccurate, or incomplete information and that I am committing a crime of the fourth degree if I make a written false statement which I do not believe to be true. I am also aware that if I knowingly direct or authorize the violation of N.J.S.A. 13:1K-6 at seq. I am personally liable for the penalties

Set TORTH M. N.J.S.A. 13					
Typed/Printed Name Mai	den vane Corporati	<u>ion</u> Title	President,	Maiden	Lane
Signature /	William at a		Corporation March 25,	n 1988	<u> </u>
Sworn to and Subscribed Before on this 25th  Date of March 19  Current B. Current Notary	88	·			

Have you enclosed a check or money order for \$100? X Yes

#### ATTACHMENT D



# State of New Jersey DEPARTMENT OF ENVIRONMENTAL PROTECTION

#### DIVISION OF HAZARDOUS WASTE MANAGEMENT

John J. Trela, Ph.D., Director 401 East State St. CN 028 Trenton, N.J. 08625 609 - 633 - 1408

Mr. Edward Evans 8-14 Saddle River Rd. Fair Lawn NJ 07410

APR 0 5 1988

RE: Dietrich St. & Gates Rd. Tract Lot 2A, B, C, D, F, G, J, Block 107 Little Ferry Borough, Bergen County #N81270

Dear Mr. Evans:

This is in response to your letter dated 3/25/88, concerning the applicability of the Environmental Cleanup Responsibility Act (ECRA) to the sale of the above referenced premises. On the basis of the sworn statements set forth in the affidavit signed by Edward Arata, the Department finds that this transaction is not subject to the provisions of ECRA.

This decision is made in light of the absence of an industrial establishment as defined within the Standard Industrial Classification numbers covered by the Act. Any inaccuracies in the affidavit or subsequent changes in the facts as stated therein could alter the Department's determination.

The inapplicability of the Environmental Cleanup Responsibility Act (ECRA) to this transaction does not relieve the above referenced of any responsibilities under any other environmental statutes, regulations or permits.

In addition, this determination of ECRA nonapplicability does not constitute any finding by the New Jersey Department of Environmental Protection as to the current site condition or existence or nonexistence of any hazards to the environment at this location.

Should you have any further questions regarding this matter, please contact me at (609) 633-7141.

Sincerely,

Thomas R Kearn
Michael DeTalvo, Supervisor

Bureau of ECRA Applicability and Compliance

### ATTACHMENT E

# JOHNSON SOILS ENGINEERING COMPANY

# PROPOSED WAREHOUSE LITTLE FERRY, N.J.

I. GENERAL: A series of six (6) borings had been made on this site in August 1972, two (2) in January 1984 and three (3) additional borings have now been completed in June 1988. The additional borings were made to fulfill requirements of the Hackensack Meadowlands Development Commission and to verify conditions where these borings were made.

The site lies between Dietrich St., Maiden Lane & the Hackensack River as shown on figure 1, the Boring Location Plan. An easement of the Bergen County Sewer Authority runs through the property. The sewer invert within this easement is at an approximate elevation of -21.

The site lies within an area designated as tidal marsh of marine origin, composed of silty clays deposited during the recession of the Wisconsin glacier. Detailed descriptions of these formations are found in the Engineering Soil Survey of New Jersey.

- II. FINDINGS: Based on review of all previous boring data & examination of the boring samples & logs from holes B-9, B-10 & B-11 we have made the following findings:
  - A. The site has been filled with a miscellaneous fill consisting of cinders, Sand, silt, wood, bricks, etc. The

fill had no inspection or control during placement. In some areas, the upper few feet are compact, however in most of the fill area the material is loose with a minimal allowable bearing capacity.

The fill depths range from 2 to 12 feet.

B. Organic SILT and/or PEAT is encountered below the fill material as follows:

> B-4 6' to 12' mixed with sand B-5 9'-13.5' B-6 8.5'-10.5' B-7 4'-14' B-9 2'-6' B-10 8'-10' B-11 6'-9'

In addition to the organic material as listed above, slightly organic SAND & SILT was encountered to the limit of exploration at 27 feet in B-7 & B-8.

C. Silty SAND is encountered below the organic layers as follows:

B-1	6.5' to 14'	B-6	10.5'-14'
B-2	7'-14'	B-9	6'-10'
B-3	9'-13.5'	B-10	10'-12'
B-4	12'-18'	B-11	9'-13'

This SAND layer is medium/dense & has an allowable bearing capacity of 3,000 pounds per square foot. The SAND layer was not encountered in B-5, B-7 & B-8.

- D. Below the fill, organic & SAND layers of holes I through 6, 9,10 & 11, typical varved SILT & CLAY formations of the Meadowlands are encountered. The upper portion of these formations is slightly stiffer & it becomes very soft with increasing depth.
- E. Glacial Till formations, consisting of red brown silty, gravelly SAND, were encountered in holes 3,5 & 6 below the varved SILT & CLAY at depths of 85 to 91.5 feet. Practical refusal was found to be at approximately 97 ft.
- III. COMMENTS: The grades of the site vary. The estimated existing grade is in the order of 6 to 8 feet. Present regulations require finish floor elevations to be at least +10. Estimated column loads are 60 to 70 kips for the proposed structure.

There are several methods that can be used to develop the site for the proposed building as follows:

- Excavation of unsuitable material and replacement with shot rock & compacted fill & then using conventional spread & continuous footings.
- 2. Friction piles--Creosoted Timber

- 4 -
- Friction piles--untreated timber below water table with concrete filled pipe pile spliced to timber pile.
- 4. End bearing piles--step tapered, pipe or "H" bearing piles.
- 5. Total surcharge of entire building area.
- Dynamic compaction with heavy falling weight.

A discussion of these methods follows:

A. Excavation & replacement -for this procedure a large backhoe is necessary with sufficient pumps to keep the excavation dry. All misc. fill & organic must be removed to the silty SAND layer which is encountered between 6 & 14 ft. below the surface.

The shot rock fill should be compacted in lifts not to exceed 2 feet in thickness. The last 3 feet below footings & slab must be a granular soil fill compacted in one ft. lifts to 95% of maximum density as determined by ASTM D-1557. The compacted fill will support footings based on design loading of 3,000 P.S.F.

For this procedure, provision must be made for disposal of the excavated organic materials, which are unsuitable for use in the building area.

- B. Friction piles using creosoted timber will require piles in the order of 55 foot lengths in order to develop a 25 ton pile. It is noted however, that because of downdrag due to the additional fill required to raise grades, the capacity of the pile for design purposes will be in the order of 15 to 20 tons depending on the amount of fill required. Use 20 tons if 2 feet or less of fill is required and 15 tons for more than 2 feet.
- C. Friction piles using untreated timber piles 50 feet in length below water table with a 15 foot splice of concrete filled corrugated pipe pile addition will develop the same loads as paragraph (B) above.
- D. End bearing piles would have to be driven to the underlying glacial till or rock at depths in the order of 100 feet +. These piles can develop bearing capacity up to 100 or more tons depending on section, however for design loads over 40 tons, a full scale load test is required.

- E. Total surcharge of entire building area would require additional fill material to be placed & compacted to proposed grade & an additional fill of 10 to 12 feet would be placed and monitored for up to a year or more. When settlement ceases, the surcharge is removed and disposed of, and the proposed structure built on spread & continuous footings using 3,000 PSF design load.
- F. Dynamic compaction of the miscellaneous fill with a heavy drop weight is not a viable alternative because of the organic layers below and the proximity of the Bergen County Sewer Authority easement and nearby resisdences.

In summary, a mat or raft foundation is not recommended because of the variation in fill & organic layer thickness with resultant differential settlement. The two methods recommended are a pile foundation or total excavation and replacement.

BORINGS - JUNE B.5 OLAM ANDRIL OIL 8-6 HS BTRICH REV 11/10/88 MAIDEN BORING LOCATION

# JURNOUN SUILS ENGINEERING LABORATORY

EXPLORATION . TESTING . DESIGN

225 GRANTWOOD BLVD. PALISADES PARK. N. J. (AREA CODE 201) 943-1793

ATTACHMENT 6-8

Industrial Center of Little Ferry, Little Ferry, N.J.

Landmark Development Corporation

		BORING LO	No1					
Depth	<u> </u>		_	_		& CORE DATA	BLOWS O	N CASING
From-To		Soil	fication of or Rock	No.	Depth From-To	Blows/6"	0-1 23	
-6.5'	Fil gra		). cinders.	1	0-2'	28-28-33- 31 LH	1-2 48 2-3 42 3-4 53 4-5 61	50-51 51-52 52-53 53-54
				2	2'-4'	18-29-26- 30 LH	5-6 <u>42</u> 6-7 <u>23</u> 7-8 <u>24</u>	54-55 55-56 56-57 57-58
.5'-14'		<b>.</b>		3	4'-6'	23-27-20- 24 LH	8-9 <u>27</u> 9-10 <u>25</u> 10-11 <u>18</u>	58-59 59-60 60-61
. JT4.	Gray silt	rine S	AND, some	4	6'-8'	18-17-15- 15		61-62 62-63 63-64
				5	8'-10' 10'-12'	8-9-10-11	14-15 <u>23</u> 15-16 <u>17</u> 16-17 <u>19</u>	64-65
-'-20'	Brow	n varve	d SILT, some	1	15'-17'	8-8-11-12 4-5-7-8	17-18 <u>22</u> 18-19 <u>24</u>	66-67 67-68 68-69
'-34!	Gray	· varved	CLAY, some	8	20'-22'	5-8-8-9	19-20 <u>23</u> 20-21 <u> </u>	69-70 70-71 71-72
	silt	•		9	25'-27'	3-4-4-4	22-23 23-24 24-25	72-73 73-74 74-75
		,		10	30'-32'	3-3-4-5	25-26 26-27 27-28	75-76 75-76 76-77 77-78
.	LH =	Large H	ammer.				28-29 29-30 30-31	78-79 79-80 80-81
							31-32 32-33 33-34	81-82 82-83 83-84
							34-35 35-36 36-37 37-38	84-85 85-86 86-87 87-88
GROU	ND WA	ATER	<b>D</b> • • •	<del></del>	300		38-39	88-89
Depth	Hour	Date	Drive H	ammer .	18"	lbs.		89-90 90-91
6'8"		<del> </del>				drop	41-42	91-92
0 8	<del></del>	9 Aug.	Spoon H	lammer .	140	lbs.		92-93
		-		_	30"	drop	44-45	93-94 94-95
			Casing	Size	2½	inch		95-96
			Spoon S	ize	2	inch '	_	96-97 97-98
						inch		77-98 98-99

THE TOTAL TOTAL PRINCEPHING PURCHULING

### EXPLORATION - TESTING - DESIGN

225 GRANTWOOD BLVD. PALISADES PARK. N. J. (AREA CODE 201) 943-1793

Project Industrial Center of Little Ferry, Little Ferry, N.J.

Landmark Development Corporation

Job No. 3427 Boring No. 2 Date August 9 & 10, 1972

BORING LOG  Depth Classification of				SP	OON SAMPLE	& CORE DATA	BLOWS ON CASING		
Depth From-To		Classific Soil or			No.	Depth From-To	Blows/ 6 ¹¹ Core Rec.	0-1 7	50-51
-1'	Topse	oil & Ve	getat	ion.				1-2 <u>8</u> 2-3 <u>16</u> 3-4 <u>18</u>	51-52 52-53
- '-7'	Fill	- sand,	grave		1	0-2'	2-3-3-4	45 <u>20</u> 56 <u>11</u>	53-54 54-55 55-56
	brick	k, wood.		,	2	2'-4'	2-4-4-5	6-7 <u>14</u> 7-8 <u>19</u>	56-57 57-58
					3	4'-6'	3-3-4-6	8-9 <u>18</u> 9-10 <u>23</u>	58-59
-11'	Gray	fine SA	ND, so	ome	4	6'-8'	3-5-4-7	10-11 <u>17</u> 11-12 <u>20</u>	60-61 61-62
	silt.	•			5	8'-10'	4-4-6-8		62-63 63-64
.'-14'	Brown of si	r F/M SA	ND, tı	race	6	10'-12'	4-6-8-8	14-15 <u>26</u> 15-16 <u>18</u> 16-17 <u>20</u>	65-66
·'-32'		urved	STLT		7	15'17'	4-6-7-8	17-18 23 18-19 22	67-68
		clay.	. UILI,	•	8	20'-22'	4-4-6-6	19-20 <u>24</u> 20-21	
					9	25'-27'	4-5-7-6	21-22 DE	71-72
					10	30'-32'	3-4-4-5	23-24 <del>                                     </del>	
								25-26 26-27	76-77
		•						27-28 28-29	. 78-79
•								29-30 30-31 31-32	80-81
	!							32-33 33-34	82-83
		1						34-35 35-36	. 84-85
								36-37 37-38	. 86-87
GRO	UND WA	ATER		Drive 1	Hammer	300	lbs.	38-39 39-40	
Depth	Hour	Date	1			18"	drop	40-41 41-42	· ··· · · · · · · · · · · · · · · · ·
6'3"		Aug. 9	& 10	Spoon	Hammer	180	lbs.	42-43 43-44	92-93
					<b>.</b> .	30"	drop	43-44 44-45 45-46	94-95
		<u> </u>		_	Size _	2½ 2	inch	46-47	
				•	Size		inch	47-48	
				Core E	Bit Size _	············	inch	48-49 49-50	

# JOHNSON SOILS ENGINEERING LABORATORY

EXPLORATION - TESTING - DESIGN

225 GRANTWOOD BLVD. PALISADES PARK. N. J.

Project Industrial Center of Little Ferry, Little Ferry, N.J.

Landmark Development Corporation

SHEET 1 OF 2

	BORING LOG	_	POON SAMPLE &	CORE DATA	BLOWS ON CASIN
Depth From-To	Classification of Soil or Rock	No.	Depth From-To	Blows/ 6" Core Rec.	0-1 50-51 _
-9'	Fill - SAND, brick, wood, gravel, w/trace	1	0-2	4-5-4-5	1-2 51-52 _ 2-3 52-53 _ 3-4 53-54 _
	organic @ 9'.	2	2'-4'	5-8-7-5	4-5 54-55 _ 5-6 55-56 _
		3	4'-6'	5-2-5-5	6-7 56-57 _ 7-8 57-58 _
		4	6'-8'	2-0-2-3	8-9 58-59 _ 9-10 59-60 _
'-11'	Gray fine SAND, some silt.	5	8'-10'	2-5-8-10	10-11 60-61 _   11-12 61-62 _
1'-13'5'	Brown F/M SAND, trace of silt.	6	10'-12'	7-13-10-15	19.4
3.5'-30'	Gray-brown varved CLAY, little silt.	7	15'-17'	2-5-7-8	16-17 66-67 _ 17-18 67-68 _ 18-19 68-69 _
		8	20'-22'	2-3-3-5	19-20 69-70 _   20-21 70-71 _
		9	25'-27'	1-2-1-1	21-22 71-72 _ 22-23 72-73
0'-69'	Gray varved CLAY, trace of silt.	10	30'-32'	0-0-1-0	23-24 73-74 _ 24-25 74-75 _
		11	35'-37'	0-1-0-1	25-26 75-76 _ 26-27 76-77 _
·	,*	12 13	40'-42' 45'-47'	1-0-1-0 0-1-0-0	27-28 77-78 _ 28-29 78-79 _
,		14	50'-52'	1-0-0-0	29-30 79-80 _ 30-31 80-81 _
		15	55'-57'	1-0-0-1	31-32 81-82 _ 32-33 82-83 _
	5" casing used to 15'	16	60'-62'	0-0-0-1	33-34 83-84 _
		17	65'-67'	1-0-1-0	35-36 85-86 _ 36-37 86-87
	UND WATER Drive	<u>                                     </u>		11.	38-39 88-89
Depth	Hour   Date	nammer	<del></del>		39-40 89-90 40-41 90-91
		Hammer		·	41-42 91-92 42-43 92-93
		. ignilliter		drop	43-44 93-94
	Casing	Size			44-45 94-95 45-46 95-96
				1	46-47 96-97 47-48 97-98
	Core	it Size		inch	48-49 98-99

# JUNNSUN SUILS ENGINEERING LABORATORY

**EXPLORATION** - TESTING

225 GRANTWOOD BLVD. PALISADES PARK, N. J. (AREA CODE 201) 943.1793

Project Industrial Center of Little Ferry, Little Ferry, N.J.

Landmark Development Corporation

SHEET 2 OF 2

Job No. 3427 Boring No. 3 Date August 10, 1972

	BC	DRING LOG	·	SF	POON SAMPLE	& CORE DATA	BLOWS (	ON CASING
Depth From-To		Classificati Soil or F		No.	Depth From-To	Blows/ 6" Core Rec.	0-1	_ 50-51
				1			I-2	
'-85'	Red-1	brown vary	ved CLAY.	18	70'-72'	1-0-1-0	2-3	_ 52-53
	litt	le silt.	ved chair,		7.0 - 72	1-0-1-0	3-4	_ 53-54
				19	75'-77'	1-0-1-1	4-5	_ 54-55
	}			-	, , , ,		5-6	_ 55-56
				20	80'-82'	1-1-2-2	6-7	_ 56-57
	Į						7-8	_ 57-58
'-91.5	Red-l	brown fine	e SAND.	21	85'-87'	1-2-5-7	8-9	_ 58-59
	litt]	le silt.	,				9-10	- 59-60
				i !			10-11	- 60-61
. 5 <b>'-</b> 97 <b>'</b>		orown SANI	D & GRAVEL,	22	90'-92'	2-5-11-13	11-12	
	trace	e of silt.				2 3 -1 -3	13-14	
				23	95'-97'	26-43-54-	14-15	
					33 2.	52	15-16	· · · · ·
						ρ-2	16-17	_ 65-66
		~					17-18	
						·	18-19	_ 67-68 _ 68-69
			ļ				19-20	_
							20-21	-
							21-22	_ 70-71 _ 71-72
	Ì			i		<b>.</b>	22-23	_
	}		ļ				23-24	_ 72-73 <u></u> _ 73-74 <u></u>
	j		1				24-25	_
	1					ĺ	25-26	_
			J				26-27	
			I				27-28	_ 77-78
1	,	•	1			j	28-29	_ 78-79
			ļ				29-30	_ 76-77 _ 79-80
	}		i	.			30-31	
1							31-32	
,	j					İ	32-33	- 81-62 - 82-83
,	•		. 1	Ī		}	33-34	
ļ				i		1	34-35	- 83-87 <u></u>
!			1			1	35-36	
!			1	I			36-37	
!							37-38	- 87-88
			<u> </u>	<u>-</u> _!	<del></del>		38-39	_ 88-89
GRC	OUND WA	ATER	Drive H	lammer	300		39-40	89-90
Depth	Hour	Date		141111114.	18"		40-41	90-91
		+				drop	41-42	. 91-92
6' 2	2 PM	10 Aug	Spoon H	Hammer	140	lbs.	42-43 43-44	. 92-93 <u> </u>
		,			30"	drop	44-45	. 93-94 <u> </u>
		-	Casina	Si-a	5	inch	45-46	. 95-96 <u> </u>

Depth	Date	
6'	2 PM	10 Aug
		·

Drive Hammer	300	
	18"	drop
Spoon Hammer	140	lbs.
	30"	drop
Casing Size	5_	inch
Spoon Size	0	inch
Core Bit Size		inch

_	38-39	88-89
	39-40	89-90
	40-41	90-91
	41-42	91-92
1	42-43	92-93
	43-44	93-94
į	44-45	94-95
ı	45-46	95-96
١	46-47	96-97
ı	47-48	97-98
	48-49	98-99
١	49-50	99-100

ATTAC!!! E-11

## JOHNSON SOILS ENGINEERING LABUKATUKY

EXPLORATION - TESTING - DESIGN

225 GRANTWOOD BLVD. PALISADES PARK, N. J. (AREA CODE 201) 943-1793

Project Industrial Center of Little Ferry, Little Ferry, N.J.

Landmark Development Corporation

Job No. 3427 Boring No. 4 Date August 8, 1972

	BOR	ING FOE		SPC	OON SAMPLE	CORE DATA	BLOWS OF	N CASING
Depth From-To		Classification of Soil or Rock		No.	Depth From-To	Blows/ 611 Core Rec.	0-1 <u>3</u> 1-2 <u>6</u>	50-51
-6 <b>'</b>		- SAND, gra	avel,	1	0-2'	2-2-4-3	2-3 <u>4</u> 3-4 <u>7</u>	51-52 52-53 53-54
	cinde	rs, wood.		2	2'-4'	2-1-1-4	4-5 <u>11</u> 5-6 <u>8</u>	54-55 55-56
				3	4'-6'	6-11-9-10	6-7 <u>13</u> 7-8 <u>13</u>	56-57 57-58
-12'		black organ		4	6'-8'	6-3-1-1	8-9 <u>18</u> 9-10 <u>19</u>	58-59 59-60
	Fill.	mixed with	i sand	5	8'-10'	2-1-3-7	10-11 11	60-61 61-62
				.6	10'-12'	6-6-8-7	12-13 <u>16</u> 13-14 <u>23</u>	62-63 <u> </u>
2'-18'	Gray silt.	fine SAND,	little	7	15'-17'	6-8-10-11	14-15 <u>24</u> 15-16 <u>16</u> 16-17 <u>19</u>	64-65 65-66 66-67
3'-32'		varved CLAY	7,	8	20'-22'	5-5-7-7	17-18 <u>23</u> 18-19 <u>27</u>	67-68 68-69
	11001	c SIIC.		9	25'-27'	5-8-10-10	19-20 <u>28</u> 20-21 <u>16</u>	69-70 <u> </u>
				10	30'-32'	7-10-10-13	21-22 <u>19</u> 22-23 <u>23</u> 23-24 <u>21</u>	71-72 72-73
						,	24-25 <u>28</u> 25-26 <u>22</u> 26-27 <u>27</u>	73-74 74-75 75-76 76-77
							27-28 <u>31</u> 28-29 <u>34</u> 29-30 <u>39</u>	77-78 78-79 _ 79-80 _
•							30-31 31-32 32-33	80-81 _ 81-82 _ 82-83 _ 83-84 _
							33-34 34-35 35-36	84-85 <u> </u>
							36-37 37-38 38-39	. 86-87 <u></u> . 87-88 <u></u> . 88-89 <u></u>
GR	OUND WA	ATER	Drive	Hammer	300	Ibs.	39-40 40-41	89-90 <u> </u>
Depth	Hour	Date			<u> 18"</u>	drop	41-42	91-91 _
7'4"		8 Aug.	Spoon	Hammer		ibs.	42-43 43-44	92-93 93-94
					30" 2½	drop	44-45	94-95 _

Drive Hammer	300	lbs.
	18"	drop
Spoon Hammer	140	lbs.
Spoon Hammer —	30"	drop
Casing Size	2½	inch
Spoon Size	2	inch
Core Bit Size		inch

ATTACHMENT F-12

46-47 _

96-97

97-98 98-99 99-100

# JOHNSON SOILS ENGINEERING LABORATORY

EXPLORATION - TESTING - DESIGN

225 GRANTWOOD BLVD. PALISADES PARK. N. J. (AREA CODE 201) 943-1793

Project Industrial Center of Little Ferry, Little Ferry, N.J.

Landmark Development Corporation

3427 5 5 Augus

SHEET 1 OF 2

	BORING LOG	l s	POON SAMPLE	& CORE DATA	DI ONCE ON THE
Depth	Classification of		Depth	Blows/ 6"	BLOWS ON CASING
From-To	Soil or Rock	No.	From-To	Core Rec.	0-1 50-51
)-8 <b>'</b>	P:11				1-2 51-52 2-3 52-53
7-0	Fill - SAND, wood,	1	0-1'6"	1-23-72	2-3 52-53 3-4 53-54
	brick, gravel.		21/1		4-5 54-55
		2	2'4'	3-6-6-7	5-6 55-56
		3	4'-6'	8-12-9-7	6-7 56-57 _
			4 -0	0-12-9-/	7-8 57-58
		4	6'-8'	4-7-13-24	8-9 58-59
				- / 13-24	9-10 59-60
'-9'	Fill - brown S'ND,	1	]	, i	10-11 60-61   11-12 61-62
	little silt.				11-12 61-62   12-13 62-63
'-13.5'	Cross amanda CTIES C	_		_	13-14 63-64
-13.3	Gray organic SILT & PEAT.	5	8'-10'	9-4-2-2	14-15 64-65 _
	ILAI.	·			15-16 65-66
		6	10'-12'	2-3-3-3	16-17 66-67
		"	10 -12	2-3-3-3	17-18 67-68
3 <b>.5'-</b> 38'	Gray-brown varved	7	15'-17'	2-3-5-6	18-19 68-69 19-20 69-70
•	SILT, some clay,		-3 -7	2-3-3-0	
	trace of sand.	8	20'-22'	1-0-1-0	20-21 70-71   21-22 71-72
					22-23 72-73
•	į	9	25'-27'	1-1-0-1	23-24 73-74
	l				24-25 74-75
		10	30'-32'	0-1-0-1	25-26 75-76 _
		11	35'-37'		26-27 76-77
	·	++	35 - 3/	1-0-0-1	27-28 77-78
3'-43'	Gray fine SAND, trac	ce   12	40'42'	6-5-9-10	28-29 78-79 29-30 79-80
	of silt.		40 42	0-3-9-10	29-30 79-80 30-31 80-81
					31-32 81-82
3'-60'	Gray varved CLAY,	13	45'-47'	2-1-2-2	32-33 82-83
	some silt.	·			33-34 83-84
	•	14	50'-52'	0-1-1-0	34-35 84-85
					35-36 85-86
		15	55 <b>'-</b> 57 <b>'</b>	1-0-1-0	36-37 86-87
		1			37-38 87-88
GRO	UND WATER [	<b>Piva</b> Hammer		lbs.	38-39 88-89 39-40 89-90
Depth	Hour Date	rify i idililiidi			39-40 89-90 40-41 90-91
	THE SET OF			drop	41-42 91-92
	s	poon Hammer	<del></del>	Ibs.	42-43 92-93
		•		drop	43-44 93-94
				•	44-45 94-95
-		Casing Size		inch	45-46 95-96
	•	noon Sire		inch	46-47 96-97

Core Bit Size

inch

47-48 _____

48-49 ____

49-50 _

97-98

98-99

ATTACHMENT E-13

99-100

# JOHNSON SOILS ENGINEERING LABORATORY

EXPLORATION - TESTING - DESIGN

225 GRANTWOOD BLVD. PALISADES PARK. N. J. (AREA CODE 201) 943-1793

Project Industrial Center of Little Ferry, Little Ferry, N.J.

Landmark Development Corporation

SHEET 2 OF 2

Job No. 3427 Boring No. 5 Date August 9, 1972

	BORING LOG	SF	POON SAMPLE &		BLOWS C	N CASING
Depth From-To	Classification of Soil or Rock	No.	Depth From-To	Blows/ 6 TO Core Rec.	0-1	50-51 51-52
60'-91.5'		16	60'-62'	1-2-2-2	2-3 3-4	51-52 52-53 53-54
00 -91.3	Ked-prown varved omir.	17	65'-67'	1-1-1-1	4-5 5-6	54-55 55-56
		18	70'-72'	0-1-1-1	6-7 7-8	56-57 57-58
		19	75'-77'	0-1-1-0	8-9 9-10	_ 58-59
		20	80'-82'	1-2-2-2	10-11	_ 60-61
		21	85'-87'	1-0-2-3	12-13	
		22	90'-92'	1-1-2-4	14-15	_ 65-66
91.5'-	Red-brown SAND, little	23	95'-97'	8-17-31-	16-17 17-18	67-68
97'	silt, trace of gravel.			86	18-19	69-70
					20-21	71-72
•				,	22-23	73-74
					24-25 25-26	75-76
				** **	26-27 27-28	77-78
	151			•	28-29 29-30	79-80
	5" casing used to 15'.				30-31	81-82
		į			32-33 33-34 34-35	83-84
					35-36 36-37	85-86 86-87
					37-38 38-39	87-88 88-89
	ROUND WATER Drive	Hamm		lbs.	39-40 40-41	89-90 90-91
- 01	COULD ALVIER		18"	1	70-71	70-71

#### GROUND WATER

Depth	Hour	Date
6'	4 PM	9 Aug.

Drive Hammer	300	lbs.
Duta Hammer	18"	drop
Spoon Hammer	140	lbs.
<b>5</b> poon 1 10	30"	drop
Casing Size	5	inch
Spoon Size	2	inch
Core Bit Size		inch

49-50 _____ ATTACHMENT E-14

91-92 _

92-93 _

93-94 _ 94-95 ___

95-96 ___

96-97 ___

97-98 ___

98-99 _ 99-100 _

41-42 _____

42-43 _____

43-44 _____

44-45 _____

45-46 _____

46-47 _____

47-48 .

#### JOKNSUN SUILS ENGINEEKING LADUNATUR

EXPLORATION - TESTING - DESIGN

225 GRANTWOOD BLVD. PALISADES PARK. N. J. (AREA CODE 201) 943-1793

Project Industrial Center of Little Ferry, Little Ferry, N.J.

Landmark Development Corporation

SHEET 1 OF 2

Job No. 3427 Boring No. 6 Date August 8 & 9, 1972

	BORING LOG	SF	OON SAMPLE &		BLOWS ON CASING
Depth From-To	Classification of Soil or Rock	No.	Depth From-To	Blows/ 6" Core Rec.	0-1 50-51 1-2 51-52
			0'1"-10"	17-21-37-	2-3 52-53
·8.5'	Fill - wood, sand,	1	0 1 -10	71	3-4 53-54
	gravel, organic SILT.			$\frac{7\pi}{2}$	4-5 54-55
		2	2'-2'9"	60 - 100	5-6 55-56
		2	2 -2 9	$\frac{100}{300}$	6-7 56-57 _
					7-8 57-58
		3	4'-4'6"	100	8-9 58-59
		5	-	<del>-6"</del>	9-10 59-60
					10-11 60-61 _
		4	6'-8'	9-1-2-7	11-12 61-62 _
		•			12-13 62-63 _
51-	Black, organic SILT.	5	8'-10'	1-1-1-2	13-14 63-64 _
10.5'	Black, organize sizzi	_			14-15 64-65 _
10.5	<u> </u>	•			15-16 65-66 _
0.5'-14'	Gray fine SAND, some	6	10'-12'	4-7-9-10	16-17 66-67 _
0.5 14	silt.				17-18 67-68 _
	3220				18-19 68-69 _
4'-30'	Gray-brown CLAY, little	7	15'-17'	3-4-6-7	19-20 69-70 _
7 33	silt.			_	20-21 70-71 _
		8	20'-22'	1-2-4-5	21-22 71-72 _
		1			22-23 72-73 _
		9	25'-27'	0-1-2-4	23-24 73-74 _
			1		24-25 74-75 _ 25-26 75-76 _
0'-80'	Gray CLAY, little silt.	10	30'-32'	0-0-1-0	25-26 75-76 _ 26-27 76-77 _
		l	1		
		11	35'-37'	1-0-0-1	27-28 77-78 _ 28-29 78-79 _
	· ·	l	1		29-30 79-80
		12	40'-42'	0-0-1-0	30-31 80-81
		1			31-32 81-82
		13	45'-47'	0-0-0-0	32-33 82-83
		l			33-34 83-84
		14	50'-52'	0-0-0-0	34-35 84-85
					35-36 85-86
		15	55'-57'	0-0-0-0	36-37 86-87
		16	60'-62'	1-0-0-0	37-38 87-88
	l	1-0			38-39 88-89
	THE SALASES BY	Hamm	<b>AP</b>	lbs.	39-40 89-90
	CALLED MATER PRIVA	amm	RI		

GROUND WATER						
Depth	Hour	Date				
<b></b>						

Drive Hammer	lbs.
	drop
Spoon Hammer	lbs.
•	drop
Casing Size	inch
Spoon Size	inch
Core Bit Size	

90-91 40-41 __ 41-42 ____ 91-92 92-93 42-43 __ 93-94 43-44 _ 94-95 44-45 _ 95-96 96-97 46-47 97-98 98-99 48-49 . 99-100

ATTACHMENT E-15

#### JUNROUR GUILO ERUIREENIRU LADUNATUR

**EXPLORATION - TESTING - DESIGN** 

225 GRANTWOOD BLVD. PALISADES PARK. N. J. (AREA CODE 201) 943-1793

Project Industrial Center of Little Ferry, Little Ferry, N.J.

Landmark Development Corporation

SHEET 1 OF 2

Job No. 3427 Boring No. 6 Date August 8 & 9, 1972

	BORING LOG	SF	POON SAMPLE &	BLOWS ON CASING		
Depth From-To	Classification of Soil or Rock	No.	Depth From-To	Blows/ 6 ¹¹ Core Rec.	0-1	50-51
			01111 1011	17 01 07	1-2	51-52
-8.5'	Fill - wood, sand,	1	0'1"-10"	17-21-37-	2-3 3-4	52-53 <u> </u>
	gravel, organic SILT.			71 71	4-5	53-54 54-55
		2	2'-2'9"	60 - 100	5-6	55-56 <u> </u>
* * * * * * * * * * * * * * * * * * * *		<b>Z</b> -	2 - 2 9	00 - 100	6-7	56-57
				3	7-8	57-58 ·
		3	4'-4'6''	100	8-9	58-59
		3	4 -4 0	1 6 T	9-10	59-60
	·			0 .	10-11	60-61
-		4	6'-8'	9-1-2-7	11-12	61-62
and the second		4	0 -0	J - T - 7 - 1	12-13	
	Disale amoneia CTIT	⁻ 5	8'-10'	1-1-1-2	13-14	
.5'- 10.5'	Black, organic SILT.	ر	0 -10	T-T-T-7	14-15	
10.2	•				15-16	
0 51 1/1	Course Sime CAND	6	10'-12'	4-7-9-10	16-17	
0.5'-14'		O	10 -12	4-7-9-10	17-18	
	silt.				18-19	
4'-30'	Course house CTAY 14mmle	7	15'-17'	3-4-6-7	19-20	
4 - 30	Gray-brown CLAY, little	′	13 -17	3-4-0-/	20-21	
	silt.	8	20'-22'	1-2-4-5	21-22	
		l °	20 -22	1-2-4-5	22-23	
		9	25'-27'	0-1-2-4	23-24	
• •	and the state of t	ן ש	25 - 27	0-1-2-4	24-25	
01.001	0 0 1:441:14	10	30'-32'	0-0-1-0	25-26	
0'-80'	Gray CLAY, little silt.	1 10	30 -32	10-0-T-0	26-27	
		1,,	35'-37'	1-0-0-1	27-28	_ 76-77 _ 77-78
		11	35 -3/	1-0-0-1	28-29	
		1,0	40'-42'	6010	29-30	
		12	40'-42'	0-0-1-0		•
		١,,	1,51 2,51		30-31	
		13	45'-47'	0-0-0-0	31-32	
		١.,	501 501		1	
•		14	50'-52'	0-0-0-0	33-34	_ 83-84 _
•	***	l			34-35	
**	<b>]</b>	15	55'-57'	0-0-0-0	35-36	_ 85-86 _
	·	۱			36-37	
		16	60'-62'	1-0-0-0	37-38	_ 87-88 _
				,	38-39	88-89 _
	OUND WATER Drive	Hamme		lbs.	39-40	_ 89-90 _

ORCOTTS TOTAL								
Depth	Hour	Date						
-								
1		1						

Drive Hammer	lbs.
± 1	drop
Spoon Hammer	Ibs.
	drop
Casing Size	inch
Spoon Size	inch
Core Bit Size	inch

49-50 ____ 99-100 ____

90-91

91-92 ₋ 92-93 ₋

93-94 _

94-95 ₋ 95-96 ₋

96-97.

97-98 .

98-99

40-41 _

41-42 ___

45-46 __ 46-47 __

44-45 _____

47-48 _____

48-49 _____

### EXPLORATION - TESTING - DESIGN

225 GRANTWOOD BLVD. PALISADES PARK, N. J. (AREA CODE 201) 943.1793

Project Industrial Center of Little Ferry, Little Ferry, N.J.

Landmark Development Corporation

SHEET 2 OF 2

Job No. 3427 Boring No. 6 Date August 8 & 9, 1972

	ВС	DRING LOG		SPOON SAMPLE & CORE DATA			BLOWS ON CASING	
Depth From-To		Classifica Soil or		No.	Depth From-To	Blows/ 6" Core Rec.	0-1	_ 50-51
				17	65'-67'	1-0-1-0	1-2 2-3 3-4	_ 51-52 _ 52-53 _ 53-54
				18	70'-72'	1-0-0-1	4-5 5-6	- 54-55 - 55-56
				19	75 <b>'-</b> 77 <b>'</b>	1-0-1-1	6-7 7-8	_ 56-57 _ 57-58 <u></u>
)'-88'5'			AY, little	20	80'-82'	1-1-2-3	8-9 9-10	58-59
	silt	•		21	85'-87'	0-2-2-3	10-11 11-12	60-61
3 <b>.5'-</b> 97'		brown SAM		22	90'-92'	14-13-23- 42	12-13	62-63 63-64
	J	, ===0.	<del> •</del> •	23	95'-97'	20-41-58-	14-15 15-16 16-17	65-66
						76	17-18 18-19	. 67-68
							19-20 20-21	_ 69-70 <u></u> _ 70-71 <u></u>
							21-22 22-23	72-73
					•		23-24 24-25	74-75
						·	25-26 26-27	_ 76-77
·		, <del>-</del>					27-28 28-29 29-30	_ 78-79
							30-31 31-32	80-81
	5" ca	asing use	ed to 15'.				32-33 33-34	82-83
							34-35 35-36	84-85
							36-37 37-38	_ 86-87
GRO	UND W	ATER	Drive I	- - - - - - - -	300	lbs.	38-39 39-40	_ 88-89 _ 89-90
Depth	Hour	Date			18"	drop	40-41 41-42	
5'3"	9 AM	Aug.9	Spoon	Hammer		lbs.	42-43 43-44	. 92-93
	<del></del>				30"	drop	44-45	. 94-95
		·			5	inch	45-46 46-47	
			Spoon	Size	2	inch	47-48	

BORING LOG #/					
Proposed Townhouses-Little Telly, January 5,1984					
Sample #	Sample Spoon Blows /6"	Casing Blows/ft.	DESCRIPTION		
1 2 3 4	6-3- 2-3 3-3- 2-3 1-2- 1-2 2-1- 1-1 2-1- 2-1	-	Fill- Sand, Silt, Cinders  w/wood & metal  0-4'  gr. organic silt		
6	1-1-2-3		4'-14'		
7	3-3- 5-6 WOH-1- 2-3	-	gr. fine SAND & silt, trace organic decreasing with depth		
5 - 9 5 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	4-5- 5-6		14'-27'		
35 -					
	narks:	3'	OH= Weight of Hammer  Date 1/5/84   Casing Hammer Wgt. ; Drop Spoon Hammer Wgt. 140#; Drop 30" Casing size ; Spoon size 2"		
Driller WARREN GEORGE INC. Casing size; Spoon size					

_{olect} Proposed	l Tov	whouses-Little Ferry, NJ-Boswell Engr Job # 5594	
te January 5			
Sample # Sample Spoon Blows /6"	Casing Blows/ft.	DESCRIPTION	
1 3-2- 2-2 3-5- 7-6 4-5- 5-3 50-57 5-6- 5 6-5 6-4- 6 4-5		Fill-Sand, silt, brick cinders w/wood & metal (timber @6'-7')	
0 4-5	$\Rightarrow$	0-12'	+
7 WOH-1- 2-2		gr. SILT, some fine Sand, trace organic	
8 1-2			
9 2-1- 3-3		12'-27'	
		The second of th	
emarks:	WOH=	Weight of Hammer	
epth to Water 4 '		Date 1/5/84 Casing Hammer Wgt. ; Drop	1
Driller WARREN GEORGE INC. Spoon Hammer Wgt. 140#;Drop 30" Casing size; Spoon size;			
	ews.	ATTACHMEN	VT E-V

Pro	Project Proposed Warehouse, Notorangelo, Little Ferry, NJ Job# 6991					
Dat	Date June 21,1988					
Depth, Feet	Sample #	Sample Spoon Blows /6"	Casing Blows/ft.		DESCRIPTION	-
-	1	100/3"	1	Mic. Fil & CINDER	l-SAND, SILT, BRICKS	0-2'
-   5	. 3	4-3- 3-3 1-4- 5-7		Black Or	ganic SILT & PEAT	2'-6'
10 -	4	15-21- 24-27		Brown fi	ne SAND, some silt	
- - 10	5	14-23- 27-29				6'-10'
- 	6	5-5- 6-6			ay varved SILT & CLAY, fine sand	
15 - -	7	4-5- 5 <b>-</b> 5				
20 -	8	3-4-4-4				
25 - 	9	WOH-1- 1-1			·	
30 -	10	WOH-1-				
35	11	1-1-				10'-37'
40						
R	ema	rks: wo	H= W	eight of Hammer		
	epth	to Water	7'	Date 6/21/88	Casing Hammer Wgt.  Spoon Hammer Wgt. 140#;	; Drop 30"
Driller FRANK GREGORY INC. Casing size ; Spoon size 2"						

,				_of	
Project Proposed Warehouse, Notorangelo, Little Ferry, NJ Job # 6991					
Date					
Depth, Feet	Sample Spoon Blows /6"	Casing Blows/ft.	DESCRIPTION		
1	7-100				
5 - 2	14-4-	<b>-</b>	Misc. Fill-SAND, SILT, GRAVEL, BROKEN CONCRETE	0-6'	
1 🖠	5-13		Gray fine/medium SAND, little silt	6'-8'	
10 -			Black organic SILT & PEAT	8'-10'	
3	11-9- 12-13		Gray fine/medium SAND & SILT	10'-12'	
115 - 4	4-6- 5-6		Dark gray varved SILT & CLAY, trace of fine sand		
<b>20 -</b> 5	4-5- 6-6				
<b>25 -</b> 6	3-4- 8-4				
<b>30</b> - 7	5-6- 6-7				
35-	8 4-5-4-4			12'-27'	
40-	:				
Rema	Remarks:				
			Casing Hammer Wgt. ;  Spoon Hammer Wgt. 140#; Dr.  Casing size ;  Spoon si	Drop	
Driller FRANK GREGORY INC. Casing size ; Spoon size 2"					

## JOHNSON SOILS ENGINEERING

Project Proposed Warehouse, Notorangelo, Little Ferry, NJ Job# 6991  Date June 27,1988  DESCRIPTION  1 9-14-	in the second
Sample Spoon Casing Blows /ft.	
9-14-	And the state of t
1 20-21 9-10- 2 11-14 Misc. Fill: SAND, SILT, GRAVEL	
5-3 3-3- 3-1 1-3- 5-6 4-4- Black PEAT & organic SILT 6'-9'	í 3
Gray brown fine/medium SAND  6 4-6- 6-6  Gray brown fine/medium SAND & SILT, trace clay & organic  9'-13'	
Dark gray varved SILT & CLAY, trace of fine Sand	·
20 - 8 4-5- 5-6	
25 - 9 4-4- 5-5	÷
30 - -10 6-6- 5-6	Î ₩ dec. care
135- 11 4-5- 5-5	
40-	
Remarks:	A Company
Depth to Water 8' Date 6/27/88 Casing Hammer Wgt.; Drop  Spoon Hammer Wgt. 140#; Drop 30" Casing size ; Spoon size 2"  ATTACHMENT	E-22

## ATTACHMENT F

5, to to the north.

MEMO	NEW JERSEY STATE DEPARTMENT OF ENVIRONMENTAL PROTECTIO
TO File	1.1.
FROM David Been	ar-
SUBJECT Dietrick St.	9 Gates Rd Travt.
	phs revened in Tranton reveal that
the Subject site	was not a landfill since at least
_	is proporty confised with a fill

ATTACHMENT G



FEB & 0 IGRA

KATHERINE STREET

(201) 641-9234

A. TEDESCO, JR. MAYOR

February 22, 1989

MARCO SAVINO ADMINISTRATOR/TREASURER

12-30-18

State of N.J. Dept. of Environmental Protection Div. of Hazardous Waste Management 402 E. State St. CN 028 Trenton, N.J. 08625

Mr. Michael DeTalvo, Supervisor Bureau of ECRA Applicability and

Compliance

Dietrich Industrial Re:

Block 107

Lots 2A,B,C,D,F,G,J

Dear Mr. DeTalvo:

The above-referenced applicant has sent us a copy of a letter which you sent to Mr. Edward Evans on April 5, 1988 concerning the above-captioned property. We are enclosing a copy of this letter for your ready reference.

Please be advised that, sometime in the past, this was the site of a sewage treatment plant and various chemicals were dumped on this site. It has come to our attention that test borings were made but they were made in only one place.

We would greatly appeciate any assistance you can render in this matter and hopefully furnishing us with same prior to our next workshop meeting, which will be on March 15, 1989.

Thanking you in advance for your anticipated cooperation with regard to the above, I remain,

Very truly yours.

Mary C/ Fiant, Clerk

Planning Board

cc: Planning Board

ATTACHMENT H

Borough of Little Ferry LITTLE FERRY, N. J. 07643 ONE KATHERINE STREET (201) 641-9234 MAYOR MARCO SAVINO

February 28, 1989

Mr. David Beeman Div. of Hazardous Waste Management Metro Enforcement 2 Babcock Place West Orange, N.J. 07052

> Re: Dietrich Industrial Block 107

Lots 2A,B,C,D,F,G,J

ADMINISTRATOR/TREASURER

Dear Mr. Beeman:

In accordance with our conversation of this date, I understand that the above matter has been turned over to you because it is not under ECRA's jursidiction.

As you know, the above-captioned property was the site of a sewer plant operated by the Borough between approximately 1930 and 1957.

For your information, I am enclosing a copy of a recent study on Soils Investigation submitted by Johnson Soils Engineering Co.

We would appreciate hearing from you prior to our workshop meeting on February 15th or prior to our public meeting which will be on February 22nd.

Thanking you in advance for your cooperation, I remain.

James Busico 66 Plandin hans 1-14/k Fary 641-6276

Very truly yours,

Mary Co Fiant, Clerk Planning Board

=m phatore

### ATTACHMENT I

For: Boswell Engineering South Hackensack, NJ

Soils Investigation

Notarangelo Property Little Ferry, NJ

By: Lois A. Spagnola
Allied Environmental
Industries Corporation

# Table of Contents

		Page	
Letter/Summation		1 - 2	
Site Map		3	
Table I/Sample Results	1	4 - 5	
Site Specific QA/QC		Addendum	I
Resume/Oualifications		Addendum	II

April 14, 1989

Mr. Kevin Boswell BOSWELL ENGINEERING CO. 330 Phillips Avenue South Hackensack, NJ 07606

Dear Mr. Boswell:

The sampling as discussed was performed on April 11, 1989. The following is a report of the analytical results of the sampling.

Samples were taken from seven (7) locations (addendum I - Site Map). Groundwater was discovered at approximately four (4) feet below grade, except for Location 1, where it was found to be approximately six (6) feet below grade. Therefore, samples include a composite of soils above and below groundwater level encountered during sampling. Because petroleum hydrocarbons (PHC) will float on water, it is believed that any PHC results will be a good indication of the order of magnitude of the problem. Two (2) samples were taken from Location 1A in order to determine whether there is a discrepancy in contamination levels at greater depths.

Volatile Organia Compannis (VOC) were also sampled for because they are often indicative or contamination which could seriously degrade the quality of groundwater. The New Jersey Department of Environmental Protection (NJDEP) standard requires that samples for VOC's be taken for at least two (2) feet below ground. This standard was met for the purpose of this report.

The property is overgrown, with no visible signs of dumping; however, construction debris and rubbish were found in Locations 4A-7A.

Table 1 lists all sampling results. There were no VOC's detected at any of the sample locations. The PHC results detected to 514 milligrams per kilogram (mg/kg). The highest level of PHC's was found in the area closest to the Hackensack

April 14, 1989 Page 2

Mr. Kevin Boswell BOSWELL ENGINEERING CO. 330 Phillips Avenue South Hackensack, NJ 07606

River. It should also be noted that any asphalt in the samples (asphalt was encountered in much of the debris) would show up as PHC in the analytical results.

The minimal levels of PHC's are probably the result of these factors:

- PHC's are in fact typical in a body of water such as the Hackensack River that is tidal in this area.
- The former presence of above ground oil storage tanks to the south of the property.
- The presence of contaminated debris on the site.

The PHC results found were relatively low and are most probably present in this and all sites fronting the Hackensack River and are the result of years of tidal action/flooding by the Hackensack liver. The result ment below the livels which the MDFR uses to retermine whether oil-contaminated toil can be disposed of in state, which is 30,000 mg/kg. Typically in cases such as this, the MDFR ward and require to the live.

soils because the area would become recontaminated as a result of continuous flooding by the Hackensack River. Based on site inspections, soil boring, and analytical results, it is the opinion of Allied Environmental Industries Corporation that this property is of minor environmental concern.

Very truly yours,

Lois A. Spagnola

LAS/pjw




Table 1
Sample Results

Sample #	Composite Depth	Analysis. Conducted	Results
LFS 1A	0'-4'	PHC VOC	ND ND
LFS 1B	0'-6'	PHC VOC	ND ND
LFS 2A	0'-4'	PHC VOC	15mg/kg ND
LFS 3A	0'-4'	PHC VOC	167mg/kg ND
LFS 4A	0'-4'	PHC VOC	20 mg/kg ND
LFS 5A	0'-4'	PHC VOC	30 mg/kg ND
LFS 6A	0'-4'	PHC VOC	ND ND
LFS 7A	0'-4'	PHC NGC	514 mg/kg ND

#### ALLIED ENVIRONMENTAL

Veritech Laboratory Log Sheet **美国建筑建筑建筑建筑设设设设设设设设** LAB ND: 4130-36

Date Received: 4/12/89

Received By: 8G

Date Completed: 4/12/89

CGC No.: 041289-1

Date Reported: 4/13/89

NJDEP Laboratory No. 14622

Invoice No. 1

Client: ALLIED ENVIRONMENTAL Project No.: NOTARANGELO HACKENSACK, NJ Address 271 RT. 46 WEST, SUITE DE01, FAIRFIELD, NJ 07006

Client Contact: LOIS SPAGNOLA

These Nort Ected TEE

Invoice To: CAMI

Passion Neaded Try 0/10/09 Demplors

Sample Matrix: Liquid( ) Solid(X) Sludge( ) Mixed( )

Sample Type: Wastewater( ) Product( ) Groundwater( ) Boil(X) Waste()

Sample For: Product GA/GC( ) Wastewater( ) ECRA( ) RCRA( )

Deliverables: Results Only(X) Tier Il()

#### NOTES :

This report is a true report of results obtained from our tests of this material. In lieu of a formal contract document the total apprepate liability of Veritech to all parties shall not exceed Veritech's total fee for analytical services rendered.

Laboratory Manager



April 21, 1989

LAS: Notavangelo.

Mr. Kevin Boswell BOSWELL ENGINEERING CO. 330 Phillips Avenue South Hackensack, NJ 07606

Re: April 14, 1989: Notarangelo Property

Little Ferry, New Jersey

Dear Mr. Boswell,

I offer the following information as additions to the above referenced site report:

#### Addendum I

Quality control for sampling performed. Please note that all NJDEP standards were met.

#### Addendum II

My resume and qualifications. Also note that I am a recognized expert in hazardous and non-hazardous value the remodiation, most recently in trial before the Honorable William H. Walls, Superior Court, County of Essex, in the case of "Juno vs. Simon, " Docket no. W41301-88E.

Should you require additional information, please do not hesitate to contact me at (201) 808-1755.

Very truly yours,

Lois A. Spagnola

LAS/pjw

cc: William Fourgerel

Frank Rusch

ATTACHMENT J

. .



## State of New Jersey

### DEPARTMENT OF ENVIRONMENTAL PROTECTION

DIVISION OF HAZARDOUS WASTE MANAGEMENT

CN 028 Trenton, N.J. 08625-0028 (609) 633-1408 Fax # (609) 633-1454

March 22, 1991

Frank Notarangelo Notarangelo Carting 251 2nd Street Saddlebrook, New Jersey

Re: NJDEP Investigation of Block 107, Lots 2.01 and 17, Little Ferry, New Jersey

Dear Mr. Notarangelo:

Under the Comprehensive Environmental Response, Compensation and Liability Act (CERCIA) of 1980 and the Superfund Amendments Reauthorization Act (SARA) of 1986, the U.S. Environmental Protection Agency (USEPA) has been granted the authority to investigate known and suspected releases to the environment. This authority has been conferred to the New Jersey Department of Environmental Protection (NJDEP) under a grant from the USEPA.

A requirement of the investigative process is for the NJDEP, Bureau of Planning and Assessment to conduct a Pre-Sampling Assessment of your facility to determine if any hazardous conditions exist, and to assess if environmental sampling is warranted for your facility.

This Bureau intends to conduct a Pre-Sampling Assessment of your facility. As per my March 21, 1991 phone discussion with Bill Fourgerel, I will contact Lois Spagnola on March 25, 1991 to arrange a date.



If you have any further questions please feel free to contact me at (609) 584-4332.

Thank you for your anticipated cooperation.

Sincerely,

Karen Hiering

HSMS IV

NJDEP, Division of Hazardous Waste Management, Bureau of Planning and Assessment

KH:mz